

January 26, 1972

Gran -
This is the
best we can
do at the
moment based
on the emergency
standard.

to Asbestos Dust

ssive exposure to asbestos dust, the fol-
lowing must be followed when working with or han-
dling asbestos cement, mortar, coatings, grout

... .. Sweeping is permitted when cleaning up
asbestos or asbestos dust.

- (2) Asbestos waste, scrap and dust must be placed in closed containers until it is disposed of. (Use shipping carton or bag when cleaning up job)
- (3) Dust particulate respirators must be worn when exposure exceeds 15 minutes of an 8 hour day while performing any of the following operations:
 - A. Removing asbestos insulation from vessels, piping, structures or buildings.
 - B. Cleaning up asbestos waste, dust or scrap.
 - C. Loading or unloading asbestos or asbestos cement, mortar, coatings, grout and plaster.
 - D. Restacking or handling of asbestos in cardboard shipping containers.
 - E. Fabricating and/or installing asbestos insulation.
- (4) Dust particulate respirators must be worn at all times while mixing asbestos cements, mortars, coatings, grout and plaster.

7-0. 180.4
January 26, 1972

TO: B&R Personnel

SUBJECT: Exposure to Asbestos Dust

To avoid excessive exposure to asbestos dust, the following procedure must be followed when working with or handling asbestos or asbestos cement, mortar, coatings, grout and plaster:

- (1) No dry sweeping is permitted when cleaning up asbestos or asbestos dust.
- (2) Asbestos waste, scrap and dust must be placed in closed containers until it is disposed of. (Use shipping carton or bag when cleaning up job)
- (3) Dust particulate^{LE} respirators must be worn when exposure exceeds 15 minutes of an 8 hour day while performing any of the following operations:
 - A. Removing asbestos insulation from vessels, piping, structures or buildings.
 - B. Cleaning up asbestos waste, dust or scrap.
 - C. Loading or unloading asbestos or asbestos cement, mortar, coatings, grout and plaster.
 - D. Restacking or handling of asbestos in cardboard shipping containers. - 1
 - E. Fabricating and/or installing asbestos insulation.
- (4) Dust particulate^{LE} respirators must be worn at all times while mixing asbestos cements, mortars, coatings, grout and plaster.

DE 009437

SUBJ: Exposure to Asbestos Dust (Cont'd)
DATE: January 26, 1972

- (5) Dust particat^{LE} respirators must be worn at all
times while performing any task with asbestos
materials inside enclosed structures or buildings.
- (6) The Wilson style 600A Mono-mask that is available
from the tool room is to be used as a dust parti-
cal^{LE} respirator until further notice.

Jerry DeLay