Monsanto — **CALL REPORT – ORGANIC DIVISION**

DICTATE IN SEQUENCE:
1. HEADING INFORMATION
2. NAMES OF ADDRESSEES
3. NAMES OF CARBONEES
4. IMMEDIATE ACTION NEEDED
5. REPORT ON CALL

REPORT CAPTIONS:
1. OBJECTIVE
2. PERSONS CONTACTED
3. RESULTS
4. ACTION REQUIRED

CUSTOMER NAME		DATE OF CALL
THIOKOL CHEMICAL		3-12-71
CITY AND STATE	DATE RECEIVED	DATE TYPED
TRENTON, NEW JERSEY	3-15-71	3-17-71

CUSTOMER MAILING LIST CHANGES – SERVICE CENTER USE ONLY

NAME AND TITLE	PUT ON	TAKE OFF	MP	MAG.	CATEGORY CODES

REGION	SERVICE CENTER	SALESMAN
Northeast	New York	Jan Smoke/lbh

TO Dr. C. P. Farley
St. Louis

CC E. H. Fording - New York
Al Morgan - Queeny
~~Don Denby~~ - ~~St. Louis~~
Willis Clark - St. Louis
J. R. Darby - Queeny

Contacted:

Bill Overberger - Technical Service Manager
~~John Gallagher - Sales Manager~~

Objectives:

(1) Discuss our new XA-358.
(2) Check Thiokol ZP-680 plasticizer.
(3) Ask about polysulfide business.

Results:

(1) Bill promised us a quick evaluation of XA-358 as the screening data loo pretty good. I'll check him on this in about three weeks.

(2) Thiokol is making ZP-680, rather than having it made for them. Bill does not regard ZP-680 as a "cure-all" for polysulfide plasticizer problems. He feels with a sample we can easily identify what it is. Will obtain a sample and forward to Al Morgan.

(3) Bill says Chrysler will switch away from polysulfide sealants to butyl tapes. That leaves GM alone as a polysulfide user among the auto companies. Our Aroclor 1254 withdrawal continues to cause many problem mainly because A-1254 exhibits superior lead paste stability in two par systems. S-261 is more and more the choice of Thiokol. Many chlorinated paraffins cause "blowing", or bubbling of the sealant, when subjected to water immersion.

~~Jan Smoke~~
New York Office

S-331 (REV. 12/68)

0462798

1 – CENTRAL OFFICE COPY

HARTOLDMON0004716