

R96846D - B.F.G. PERSONNEL MONITOR - PERSONAL DATA

01/01/76 TO 12/31/76

DATE 03/10/77 TIME 120230 PAGE

1

CHEMICAL M1

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH F
HENRY	732	000	030	C	111576	360	.14	OUT MASK	NO
HENRY	732	000	030	B	120276	350	.35	OUT MASK	>20%

* B F G R E

R96846

VCM MONITORING - PERSONAL RECORD

DATE 01/15/76

FROM 01/01/75 TO 12/31/75

PLANT NAME	SPL.PERIOD	AREA	TASK	JOB	SHIFT	DATE	EXPD.TIME	PM-VCM	R
HENRY	LONG	732	000	030	B	052875	360	0.07	0
HENRY	LONG	732	000	030	C	091975	360	0.04	0
HENRY	LONG	732	000	030	D	122375	360	0.13	0

R96846D - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/77 TO 12/31/77 DATE 01/04/78 TIME 131644 PAGE 1

CHEMICAL M1										MALE	
PLANT NAME	AREA	TASK	JOB	SHIFT	DATE	E/T	PPM	PUMP	PBS	BRK TH	RESP
HENRY	732	000	027	C	030377	360	.26	OUT	MASK	ND	0
HENRY	732	000	030	A	070877	360	1.18	OUT	MASK	>20%	0
HENRY	732	000	030	A	092977	360	1.00	OUT	MASK	ND	0
HENRY	732	000	030	B	110777	360	1.72	OUT	MASK	ND	0
HENRY	732	000	030	B	120277	360	3.18	OUT	MASK	ND	0

NGC 11766

R9684CD - B.F.G. PERSONNEL MONITOR - PERSONAL DATA

01/01/78 TO 12/31/78

DATE 01/18/79 TIME 080117 PAGE

1

CHEMICAL M1 MALE										
PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP PDS	BRK TH	RES
HENRY	732	000	030	B	010478	360	.69	OUT MASK	NO	C
HENRY	732	000	027	C	020378	360	.52	OUT MASK	>20%	C
HENRY	733	028	032	D	073179	015	.25	OUT MASK	NO	2
HENRY	733	000	031	B	101078	360	1.82	OUT MASK	NO	2
HENRY	735	000	030	C	030378	360	2.94	OUT MASK	NO	0
HENRY	735	000	030	B	032378	360	.44	OUT MASK	NO	C
HENRY	735	000	030	C	033178	360	1.13	OUT MASK	NO	0
HENRY	735	000	030	A	041378	360	1.39	OUT MASK	NO	C
HENRY	735	000	030	B	042478	360	.70	OUT MASK	NO	0
HENRY	735	000	030	C	050178	360	.22	OUT MASK	NO	2
HENRY	735	000	030	C	053078	360	.11	OUT MASK	NO	0
HENRY	735	000	030	D	060578	360	.12	OUT MASK	NO	0
HENRY	735	000	030	C	072078	360	.72	OUT MASK	NO	0
HENRY	735	000	030	A	080478	360	.09	OUT MASK	NO	2
HENRY	735	000	030	C	091478	360	.03	OUT MASK	NO	0
HENRY	735	000	030	D	102578	360	.41	OUT MASK	NO	0
HENRY	735	000	027	B	110678	360	.82	OUT MASK	NO	0
HENRY	735	000	030	D	121878	360	.27	OUT MASK	NO	0

SOUND N90 MALE										
PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...%..	> 115DB		
HENRY	732	000	027	B	013078	390	6.16			
HENRY	732	000	027	B	020178	390	14.65			

NGC 11767

R96846D - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/79 TO 12/31/79 DATE 03/27/80 TIME 115946 PAGE 1

CHEMICAL M1 MALE

PLANT NAME...	AREA	TASK	JOB	SHIFT	DATE..	E/T	..PPM	PUMP	POS	BRK	TH	RESP
HENRY	735	00C	030	D	011779	360	.22	OUT	MASK	NO		0
HENRY	735	COC	030	A	022179	360	.19	OUT	MASK	NO		0

NGC 11768

R968460 - R.F.G. PERSONNEL MONITOR - PERSONAL DATA
 01/01/80 TO 12/31/80 DATE 02/17/81 TIME 141721 PAGE 1

PLANT NAME	AREA	TASK	JOB	SHIFT	DATE	F/T	PPM	PUMP	POS	BRK	TH	RF
HENRY	718	000	046	C	081880	360	.00	PUT	MASK	NO		
HENRY	718	000	046	B	091080	360	.05	PUT	MASK	NO		
HENRY	718	000	046	A	102380	360	.20	PUT	MASK	NO		
HENRY	735	000	046	D	121680	360	3.23	PUT	MASK	NO		