PLAINTIFF'S EXHIBIT

MON-2948

Tony,

7-15-77

Talked with Leonard Schwab, and he informed me that an 8 hour program is being presented at this time to all riggers. This program covers the care and use of slings. Leonard, does plan to follow up on this item through craft supervision and future craft safety meetings.

Weldon

SC 12676

[illegible]

#2. A study [illegible] the [illegible] HCN [illegible] problem [illegible] Hambrick [illegible] Sweden. One of the possible solutions may be a pulsesiting horn as is used in Dept. 19. Once horn is installed it will be demonstrated before [illegible].

#1 on page 2

I talked with Schwab and they have been studying this problem for the past 2 months. They are aware of the problem. The solvent will be changed on a regular basis every 2 weeks or sooner when contaminated. They are inquiring into other methods that may be available. Pumps should come from the field in a decontaminated state. Schwab said they will keep zeller info [illegible].

SC 12677

LAM013872