

FILE NAME: Westinghouse (WH)

DATE: 1948 Apr 30

DOC#: WH123

DOCUMENT DESCRIPTION: Memo RE Proper Exhaust Equipment Needed

November 1993

MYBB-0008689

CC: TRANS. & GENERATOR DIV., J. S. Askey, General Foreman, Sec. 8.

I would recommend that properly designed exhaust equipment be provided for this saw, also for any other machining operations which produce any significant amount of asbestos dust. The exhaust system should effectively carry away the dust created, and care should be taken not to create dust outside the effective area of the exhaust hood.

2007

E. C. Barnes
Industrial Hygiene Engineer

**PLAINTIFF'S
EXHIBIT**

WH-348