Directions to be Issued:

1. Adequate local mechanical exhausts shall be provided at the Kneeders (see Dr. Verma's report dated February 6,1973).

2. Adequate local mechanical exhausts shall be provided at the charge and discharge of the "dry mix line" (see Dr. Verma's report dated February 6,1973).

3. Housekeeping shall be improved and maintained at a high level in the compounding section (see the above referred report).

4. Adequate dust control measures shall be provided at the "Lodige" mixer to reduce the dissemination of asbestos dust to a minimum.

5. Adequate local mechanical exhaust shall be provided at "~~Dust~~ Scrap Saw".

6. The man working at the hand roll machine shall be provided with an approved respirator.

Recommendation:

Air sampling for asbestos should be done on a regular basis.

G. S. Rajhans

GSR:SY

G. S. Rajhans, P. Eng.