FILE NAME: Hopeman Brothers (HB)

DATE: 1970 Dec 21

DOC#: HB006

DOCUMENT DESCRIPTION: Teletype Message with Response

12/21/70 DATE

TELETYPE MESSAGE

DO NOT WRITE OR TYPE IN THIS SPACE

B.1 B10 1/4

To: BIL LOCATION S. SWIACKEY NAME

DID WE GO THROUGH SOME MARINITE AND REMOVE HAZARDOUS PRODUCTS LABELS? IF SO HOW DID THEY COME OFF? IF NOT, HOW ABOUT GETTING A BOTTOM PALLET THAT HAS BEEN AROUND FOR AWHILE AND TRY TO REMOVE LABEL. IN TALKING WITH COGGINS NO ONE IN JH HAS HAD A FIRST HAND LOOK AT LABEL STICKING PROBLEM. WE DO NOT KNOW EXTENT OF PROBLEM. HOWEVER IN HOPEMAN'S CASE IT IS IMMATERIAL WHETHER THE PROBLEM IS REA OR IMAGINARY. HOPEMAN WILL NOT ACCEPT PRODUCT WITH LABELS. PERIOD. WEBER HAS ADVISED INDUSTRIAL ACCOUNTS MUST STILL HAVE NEW COMBINATION PROOF PRODUCT AND CAUTION LABEL ON THEM. EXAMPLE OF THIS LABEL IS MARINITE 36 USING LABEL #LIN-557(HAVE REVIEWED THIS WITH WINGERTER.

T-03003 RESP. NO.

PRINT OR TYPE — BE BRIEF.

WHY FILE THIS! D. S. FISCHER SIGNER

#V

MANJM

.BILJMJM 12/21

D S FISCHER

WENT THRU LOAD OF 3/4" 10 FT MTE 36 MATL ON BOTTOM PALLET HAD BEEN IN INVENTORY SINCE 9/29 HAZARDOUX LABELS WERE REMOVABLE WITHOUT TEARING LABEL SURFACE OF PANELS WAS RELATIVELY DUST FREE ALSO SURFACE HARD PANDUX EXCEEDED 55 UNITS ALSO REMOVED LABELS FROM MTE 65 ALSO REMOVABLE IN ONE PIECE

SWIACKEY

DEFENDANT'S EXHIBIT W-193

Walter Conrad Weber Swiacki

Helen Lowe

WIRE