

→ 06-ME1-3-00
06-3-048-01
06-3-048-02
SHELL OIL COMPANY
One Shell Plaza
P. O. Box 4320
Houston, TX 77210

PLAINTIFF'S EXHIBIT

SH-508

March 6, 1989

Shell Oil Company
Houston, Texas

J. P. Chadwick
L. V. Csengery
E. de Cardenas
G. T. Karnes
H. L. Kusnetz
O. D. Long
S. L. Schertz

Shell Mining Company
Houston, Texas
I. P. Jenkins

Shell Pipeline Corporation
Houston, Texas
J. W. Holden
M. G. Kohnke

RECEIVED
NO. 2 SUPPORT
ACCT. SERVICES
Mar 9 1 02 PM '89

SUBJECT: Minutes of the Shell Senior Safety Steering Group (S⁴G)

Participants:

Members

L. V. Csengery
J. P. Chadwick*
E. de Cardenas
J. H. Holden
H. L. Kusnetz
J. H. Holden

Absent

I. P. Jenkins
G. T. Karnes
O. D. Long
S. L. Schertz

Guests

J. Davis
S. F. Flynn
G. L. Greene
M. G. Kohnke
Q. J. Machac
J. D. Ransdell*
P. J. Snyder

*Part Time

The S⁴G met on Tuesday, Feb. 21, 1988. A summary follows.

Significant Events

LAM 025973

CAB8906003

ABS-007004

cc: B. F. Aurelius
K. C. Crawford
J. Davis
S. F. Flynn
R. E. Hanson
J. B. Hite
R. R. Kienle
Q. J. Machac
K. L. Mai
D. E. Miller
J. A. Mullins

W. F. Nail
E. J. Nelson
R. A. Norton
W. H. Owen
C. F. Phillips
F. C. Politz
C. E. Ross
P. J. Snyder
J. H. Spengel
HS&E-AS (2)

LAM 025972

ABS-007003

CAB8906003

OSHA Update

Phillips commented on the recently updated OSHA standard on air contaminants (CFR 1910.1000). The locations need to start meeting the new PEL levels, but several companies have appealed the new standard. Shell now has a Port-A-Count which is a portable device to perform respiratory fit-testing in the field. Shell will ask for a variance to use this device for three standards: benzene, formaldehyde, and asbestos. Phillips also discussed the need for a corporate decision (involving Legal, E&P, S&IH) regarding worker refusal to take the emergency urinary-phenol test.

Rivard said that a tentative accord had been reached with Corporate Medical on the issue of recording pleural plaques. QJM is drafting the

CAB8906003

ABS-007005

3


LAM 025974

results.

Notes

Ransdell discussed coal tar coated asbestos felt, which is used as a lining for pipes. Problems with asbestos levels may arise when removing this lining. Functions with concerns about this issue should discuss with Ransdell/Phillips.

Yours truly,



J. L. Rivard, Manager
Regulations & Safety Services

JD:sjm

LAM 025975

CAB8906003

ABS-007006

cc: B. F. Aurelius
K. C. Crawford
J. Davis
C. D. Facciponte
S. F. Flynn
R. E. Hanson
J. B. Hite
R. R. Kienle
Q. J. Machac
K. L. Mai

D. E. Miller
W. F. Nail
E. J. Nelson
W. H. Owen
C. F. Phillips
F. C. Politz
J. D. Ransdell
C. E. Ross
J. H. Spengel
HS&E-AS (2)

LAM 025976

CAB8906003

ABS-007007