FILE NAME: Garlock (GAR)

DATE: 1975 Feb 21

DOC#: GAR056

DOCUMENT DESCRIPTION: Inspection Request

2

Ministry of Labour
Ontario

MEMORANDUM

Date: February 21, 1975

File: 355-00002-0001

To:
Dr. V.L. Tidey, Chief
Occupational Health Service
Environmental Health Services Branch
Ministry of Health
15 Overlea Blvd., 5th Floor
Toronto, Ontario.

From:
Industrial Safety Branch

INSPECTION REQUEST

PROBLEM: Since the last assessment was made in 1972 by O.S.P.B. this firm has installed a new asbestos mixer in the sheeter room, also a lot of asbestos dust on hammer mill same room and on braiding machines.

PRIORITY

EMPLOYER: Garlock of Canada Ltd.,
66 Jutland Road,
Toronto, Ontario
M8Z 2H3

I.S.B. FILE NO.: 355-00002-0001

COMPLAINT NO.:

PRIME CONTACT: E. H. Chapman, Region 07

SECONDARY CONTACT: R. Turton

REPORT DATED: February 21, 1975

INDUSTRIAL SAFETY OFFICER: W. Cotton

DIRECTOR
OCCUPATIONAL HEALTH
FEB 24 1975
PROTECTION BRANCH

J. McNair, P. Eng.
Director

pB-70
To H. Wall for air sampling 26 Feb 75

pB-71
To H.A. Nelson 24 Feb 75

Communicable Health Division
15 Overlea Boulevard, 5th floor
Toronto, Ontario M4H 1A9

Telephone: 416/965-2493

February 12, 1975

Mrs. B. Colbourn
Assistant Personnel Manager
Garlocks Canada
66 Jutland Street
Toronto, Ontario

Dear Mrs. Colbourn:

Enclosed is a copy of our Data Sheet #18 on Asbestos. The Threshold Limit Value for Asbestos fibre recommended at the present time is two fibres per millilitre that are greater than five microns in length. This value is tentative and is under review. As mentioned in our telephone conversation, the data sheet is also under review.

Yours truly,

W. L. Tidey, M.D.
Acting Director
Occupational Health Protection Branch.

DATA-SHEET #18 ✓

NOT IN COMPANY FILE

DIRECTOR
OCCUPATIONAL HEALTH
FEB 12 1975
PROTECTION BRANCH