Anniston, Alabama

November 19, 1963

R. C. Sprague
J. C. Larkin
B. M. Mathorn

VAPOR PRESSURE & THERMAL STABILITY APPARATUS

Voss thermals

O. E. Bolin

Per your request, we have evaluated the maintenance on the subject instrument and find that we are unable to maintain it at reasonable cost.

The main problem seems to be in keeping the instrument in calibration. I am informed by Brack Mathorn that it must be calibrated after each use and that the calibration takes three manhours to complete. He also informs me that he has been unable to locate and correct the trouble.

Since we are unable to locate the trouble, I recommend that the instrument be returned to R&E for checking out.

Jack C. Price

JCP/fb

0547801

HARTOLDMON0005041