DCC: Mr. Richard Davis-St. Louis
New York Office

NOTE TO DCC's: It might be very well for us to look over this matter of warning individuals about leaks in an Aroclor system. We certainly aren't too emphatic about it.

R.E.K.

February 17, 1961

Mr. Joseph P. Allen
Chief Engineer
Monsanto Laboratories
3530 Peartree Avenue
New York 69, New York

Dear Mr. Allen:

Thank you for your letter of February 14. I am happy to hear that your two employes have been discharged from the hospital and presumably have recovered. There is no antidote or specific first-aid treatment that can be advised so it would be of no value to put anything about first-aid treatment in our manual.

We do state that the vapors emitted by Aroclor at elevated temperatures are injurious upon prolonged exposure and should not be breathed. Of course, we affix the chlorinated label as required by many states. I am, however, appreciative of your suggestions and will look into this matter.

It may interest you to know that your case is only the second that I have heard of since 1940. I would be interested in knowing just how extensive the leaks were, how long, in minutes or hours, the men were exposed, and whether the exposure was for several days or for only one day.

Very truly yours,

R. Emmet Kelly, M. D.
Medical Director

REK:PH

DSW 018435

STLCOPCB4004979