


FILE NAME: Colonial Sugar Refinery (CSR)

DATE: 1963

DOC#: CSR072

DOCUMENT DESCRIPTION: Letters between CSR & A.B.A. RE High Dust Counts

241



CABLES & TELEGRAMS: "CANBITE," SYDNEY. BOX 481, G.P.O., SYDNEY

CSR BUILDING MATERIALS
DIVISION OF THE COLONIAL BREAD REFINING COMPANY LTD.
1-7 BENT STREET, SYDNEY, AUSTRALIA. 20151

No. P. 226.
21st November, 1963.

The General Superintendent,
Australian Blue Asbestos Pty. Ltd.,
PERTH.

Dear Sir,

DUST HAZARD: We understand that you are regularly sampling the dust concentration in the air at points in the mine and mill using the midget impinger.

Would you please forward us a copy of the results of these tests over the last few months indicating the dust concentration and particle size of the material caught.

For your information (and for the mine) we enclose copies of a note written by Mr. N. Irving following his visit to the mine in September.


Yours faithfully,

A. D. Johnston
pro General Manager.

Help you build better

PLAINTIFF'S
EXHIBIT

104980



No. P. 230.
13th December, 1963.

The General Superintendent,
Australian Blue Asbestos Pty. Ltd.,
PERTH.

Dear Sir,

DUST HAZARD: Your No. P. 260. The dust counts in all parts of the mill and parts of the mine are still high and we will look forward to getting readings from the same points in the first and second crushing stations after the new dust collecting system starts up in January. Are the readings as quoted generally acceptable to the Mines Inspectors?

There are some very bad spots in the mine which we hope have received attention. Could you get a similar set of readings from a mine at Kalgoorlie or elsewhere so that we can make a comparison?

Have the Mines Inspectors recently set a "safe" dust count for which we have to aim?

What is the trend during the past two or three years in the incidence of lung disease at Wittenoom among both mine and mill employees?

Yours faithfully,



pro General Manager.

He is built better

