RAPID MEMO

FOR *Handwritten* MESSAGES (MAY ALSO BE TYPED)

REYNOLDS METALS COMPANY

2

FROM: S Haynes

TO: Tom King

INSTRUCTIONS — ADDRESSOR RETAIN THIS COPY FOR FOLLOW-UP

SUBJECT: Asbestos in the Plant that is Exposed

DATE: 1/20/86

MESSAGE

There several places in the Plant that Have exposed Asbestos insulation - i.e Pipes, TANKS, vessels that Have Lost the "Cover" over the insulation Exposeing the Asbestos

To List A Few -

AREA I - The S.O.P. TANK
Various STEAM Lines

[redacted]

AREA II - Flash TANKS
Desiccators
STEAM & Liq LINES
Digester Fd TANKS

AREA III - Filter Fd TANKS (1 thru 4)
washer & Settlers
Liq Lines (washer & Sett Feed & OFL Lines)
STEAM Lines & TANKS thru out AREA

☐ REPLY IMMEDIATELY ☑ NO REPLY NECESSARY SIGNATURE

REPLY

AREA IV - #9 ESP - (with exception of E & W side
#1 thru 7 Kiln STACK (Dust coll & ESP.)
(#1/2 & 3/4 Are mineral wool)
STEAM & Liq Lines Thru out AREA

Power - STEAM Lines -
Boilers -

While we REPAIR these Problems or ATTRITION, we have no ESTABLISHED Programs TO correct the Problem

DATE REPLY FROM (SIGNATURE)

B.001403

R-98-2 (REV. 6-67)