

FRICTION MATERIALS STANDARDS INSTITUTE
588 MONROE TURNPIKE, MONROE, CT 06468
AUTOMOTIVE DATA BOOK BULLETIN #5-991
April 19, 2000

This is the last Automotive Data Book Bulletin before copy was sent to the printer for the 2000 Automotive Data Book - Library Edition.

		FRONT FMSI NO.	SYSTEM F/R	REAR FMSI NO.
<u>ACURA</u>				
2000, TL		7656-D787**	D/D	7418-D536**
2000, Integra		7493-D617**	D/D	7443-D564**
	OR	7382-D503**	D/D	7418-D536**
2000, NSX		7382-D503**	D/D	7383-D504**
<u>CHEVROLET TRUCK</u>				
Tracker	2000	7680-D807**	D/N	1506-S738*
<u>CHEV TRUCK/GMC TRUCK</u>				
Astro Van/Safari	2000	7214A-D52	D/BH	2117BTT-S651
Astro Van 4WD/Safari 4WD	2000	7259-D369**	D/BH	2117BTT-S651
Express Van G1500/ Savana G1500	2000	7259-D369**	D/BH	2073AT-S653
Express Van G2500/ Savana G2500	2000	7259-D369**	D/BH	2073AT-S653
	OR	7260-D370**	D/BH	2157AT-S656
Express Van G3500/ Savana G3500	2000	7260-D370**	D/BH	2157AT-S656
	OR	7339-D459**	D/	
<u>FORD</u>				
2000, Escort		7353-D473**	D/N	1407-S721*
	OR		/D	7514-D663**
2000, Taurus		7479-D601**	D/N	1395-599
	OR		/D	7489A-D610
2000, Taurus Wagon		7479-D601**	D/N	1396-S618
	OR		/D	7489A-D610
2000, Taurus Police		7479-D601**	D/D	7489A-D610
2000, Taurus SHO		7633-D765**	D/D	7489A-D610
2000, Mustang		7675-D804**	D/D	7504-D627**
2000, Mustang Cobra 5.0L		7300-D412**	D/D	7524-D627**
2000, Contour		7630-D762**	D/N	1479-S696*
	OR	7672-D801**	D/N	1504-S736*
	OR		/D	7541-D661**
2000, Crown Victoria		7617-D748**	D/D	7610-D674**
<u>FORD TRUCK</u>				
Expedition	2000	7576-D702**	D/D	7584-D711**
Explorer	2000	7532-D652**	D/D	7545A-D667

SEE DISCLAIMER AT END OF BULLETIN

FMSI® and FMS® are registered trademarks of the
Friction Materials Standards Institute, Inc.

Copyright© by Friction Materials Standards Institute, Inc.

		FRONT		SYSTEM	REAR
		FMSI NO.	F/R	FMSI NO.	
<u>FORD TRUCK (cont'd)</u>					
Ranger	2000	7532-D652**	D/BH	2185T-S704	
	OR		/BH	2089AT-S705	
Ranger	1999	OR	/BH	2089AT-S705	
Windstar	2000	7674-D803**	D/N	1452-S665	
	OR		/D	7543-D664**	
E150	2000	7503-D632**	D/BH	2182TT-S723*	
E250	2000	7535-D655**	D/BH	2140AT-314	
	OR		/D	7673-D802**	
E350	2000	7535-D655**	D/BH	2140AT-314	
	OR		/D	7673-D802**	
E Super Duty	2000	7535-D655**	D/D	7299-D411**	
F150	2000	7558-D679**	D/BH	2182TT-S723*	
	OR		/D	7584-D711**	
F250 Super Duty	2000	7625-D756**	D/BH	2146AT-316	
	OR		/D	7626-D757**	
F350 Super Duty	2000	7625-D756**	D/D	7626-D757**	
F450 Super Duty	2000-99	7644-D777**	D/D	7644-D777**	
F550 Super Duty	2000-99	7644-D777**	D/D	7644-D777**	
<u>HONDA</u>					
2000, Accord Coupe		7345-D465**	D/N	1429-S627*	
	OR	7382-D503**	D/D	7418-D537**	
2000, Accord Sedan		7382-D503**	D/N	1429-S627*	
	OR	7632-D764**	D/D	7418-D537**	
2000, CRV		7382-D503**	D/N	1429-S627*	
2000, Civic		7439-D560**	D/N	1364-576*	
	OR	7573-D465**	D/D	7443-D564**	
2000, Odyssey		7663-D793**	D/N	1512-S744*	
2000, Passport		7585-D579**	D/N	1509-S735*	
	OR		/D	7586-D580**	
2000, Prelude		7382-D503**	D/D	7418-D537**	
2000, S2000			/D	7418-D537**	
<u>ISUZU</u>					
2000, Amigo		7585-D579**	D/N	1509-S735*	
	OR		/D	7586-D580**	
2000, Rodeo		7585-D579**	D/N	1509-S735*	
	OR		/D	7586-D580**	
2000, Trooper		7459-D579**	D/D	7460-D580**	
2000, Vehicross		7459-D579**	D/D	7460-D580**	
<u>LINCOLN</u>					
2000, Continental		7476-D598**	D/D	7489A-D610	
2000, Town Car		7617-D748**	D/D	7610-D674**	
	OR		/BH	2182TT-S723*	
2000, Navigator		7576-D702**	D/D	7584-D711**	
<u>MERCURY</u>					
2000, Cougar		7630-D762**	D/D	7541-D661**	
2000, Grand Marquis		7617-D748**	D/D	7610-D674**	
2000, Mountaineer		7532-D652**	D/D	7545A-D667	

		FRONT	SYSTEM	REAR
		FMSI NO.	F/R	FMSI NO.
<u>MERCURY (cont'd)</u>				
2000, Mystique		7630-D762**	D/N	1479-S696*
	OR	7672-D801**	D/N	1504-S736*
	OR		/D	7541-D661**
2000, Sable		7479-D601**	D/N	1395-599
	OR		/D	7489A-D610
2000, Sable Wagon		7479-D601**	D/N	1396-S618
	OR		/D	7489A-D610
2000, Tracer		7353-D473**	D/N	1407-S721*
	OR		/D	7514-D663**
2000, Villager		7456-D576**	D/N	1452-S665
<u>NISSAN</u>				
2000, Altima		7318-D430**	D/D	7533-D540**
2000, Frontier		7228-D333**	D/N	1399-574*
2000, Maxima			/D	7533-D540**
2000, Quest		7456-D576**	D/N	1452-S665
1999, Sentra		7546-D668**	D/N	1438-S638*
	OR		/D	7547-D669**
2000, Xterra		7703-D830**	D/N	1433-S631*
	(Notes #1 & #4)			
<u>SUZUKI</u>				
2000, Swift		7331-D451**	D/N	1489-S724*
<u>TOYOTA</u>				
2000, Camry		7441-D562**	D/N	1447-587*
	OR	7581-D707**	D/D	7223-D325**
2000, Echo		7704-D831**	D/N	1518-S754*
	(Notes #2 & #5)		(Notes #3 & #6)	
2000, Land Cruiser		7639-D772**	D/D	7640-D773**
2000, Tacoma 2WD		7548-D433**	D/N	1358-505*
	OR	7671-D799**	D/N	1397-589*
2000, Tacoma 4WD		7671-D799**	D/N	1397-589*
2000, Tundra		7687-D812**	D/N	1397-589*
2000, 4-Runner		7298-D611**	D/N	1397-589*
2000, RAV-4		7441-D695**	D/N	1447-587*

DISC BRAKE LINING ASSIGNMENTS

Note #1	<u>FMSI 7703</u>	7703-D830		
7703	48.8 16.9	135.1	4	Integrally
	(1.92 .665	5.32)		Molded
(D830)				
Nissan				
Note #2	<u>FMSI 7704</u>	7704-D831		
7704	39.9 16.5	88.1	4	Integrally
	(1.57 .650	3.47)		Molded
(D831)				
Toyota				

DRUM BRAKE LINING ASSIGNMENTS

Note #3 FMSI 1518 1518-S754
 1518 182.0 25.0 3.8 171.5 4 Bonded
 (7.17 .98 .150 6.75)
 (S754)
 Toyota

DISC BRAKE SHOE ASSIGNMENTS

Note #4 FMS D830
 164.1 Plate 6.1
 SHOE D830 (6.46) (.240)
 7703
 Two shoes have sensors staked-on (LH,RH) Nissan



Note #5 FMS D831
 112.4 Plate 5.6
 SHOE D831-I (4.43) (.220)
 7704
 One shoe as shown, one shoe mirror image
 Sensors staked-on (LH,RH)

 112.4 Plate 5.6
 SHOE D831-O (4.43) (.220)
 7704



- Inner

Toyota



- Outer

Toyota

DRUM BRAKE SHOE ASSIGNMENTS

Note #6 FMS S754
 182 x 25.0 Web 2.9
 SHOE S754 (7.17 x .98) (.114)
 1518



Toyota

The data shown in this bulletin has been supplied by sources considered to be reliable. While we believe that such information is correct, the Institute cannot and does not accept any responsibility or liability for errors or omissions, or harm resulting therefrom.

The data shown in this bulletin indicates dimensions only and in no way refers to quality of any materials that may be embodied in the product or particular application involved, and moreover, SINCE FIELD CONDITIONS AND OTHER FACTS MAY NECESSARILY VARY FROM ONE APPLICATION TO ANOTHER, FRICTION MATERIALS SUPPLIERS AND INSTALLERS SHOULD RELY ULTIMATELY AND SOLELY UPON THEIR OWN EXPERTISE AND JUDGMENT AS TO QUALITY AND DIMENSIONAL SIZE. Under no circumstances should replacement items be used when they do not appear to fit, nor be "forced" to fit, nor be modified in the field instead of obtaining a proper sized item from a supplier. If such items are modified in the field to fit, the Institute specifically disclaims all liability and responsibility for any harm resulting therefrom.

If any error or omission is noted in this bulletin, it should be reported immediately to the Friction Materials Standards Institute Inc, 588 Monroe Turnpike, Monroe, Connecticut 06468.