Intra Company

January 28, 1970

Dr. Jeremiah R. Lynch
Laboratory of Engineering
Occupational Health Program
Public Health Service
Department of Health, Education and Welfare
1014 Broadway
Cincinnati, Ohio 45202

Dear Dr. Lynch:

We have been thinking about the problem of asbestos from brake linings and it has been pointed out that some fibers might indeed be present but be too small to be seen at the magnification you used in your work (JAPCA 18, 824 (1968)). Do you have any comments about this? Do you know of any further work, or plans for work, at higher magnification? We could try doing something in this area if it seemed warranted.

Sincerely yours,

William R. Pierson
Chemistry Department
Scientific Research Staff

WRP:mc

009721

PRODUCED BY FORD

8000 0061

81.22

SCF-FORD-0621