

Attachment I - Corp Newsletters to Location IH

INTERNAL CORRESPONDENCE May 4, 1964

FROM THOMAS B. BONNEY
PITTSBURGH OFFICE

TO INDUSTRIAL HYGIENE
COMMITTEE CHAIRMEN

hrc
hrc
f

RE: INDUSTRIAL HYGIENE NEWSLETTER
SAWING MARINITE

In recent months several incidents have occurred that prompted us to take a closer look at the potential problems associated with the sawing of Marinite. In the past, because of erroneous information given us about the composition of this material, we may have advised you poorly about the proper handling of it. In order to correct this, especially in view of the widespread use of Marinite, we felt that this Newsletter would be timely and appropriate.

Marinite is an insulating refractory board manufactured by Johns-Mansville. It consists of a mixture of asbestos fibers and diatomaceous earth bonded with an epoxy resin. In Alcoa it is widely used for headers in DC Casting Units and for trough linings. In order to be used for these applications, it is necessary that the Marinite first be sawed into appropriate sizes and shapes. Sawing generates a considerable amount of dust which is the main, if not the sole, cause of difficulty in handling this material. Were it not for the presence of the epoxy binder, proper control would consist simply of keeping the sawyers' time-weighted exposures below 5 mppcf, the threshold limit value for asbestos. However, the epoxy binder complicates the picture.

Although the surface of a cured epoxy resin system is almost completely inert, this is not true of the interior structure which contains an appreciable amount of unreacted resin and hardener. As a result, dusts from machining and sawing epoxy resin systems are likely to be quite irritating. Dermatitis from

83-3875-09000-002 #6

Category Code

APC 004272

PLAINTIFF'S
EXHIBIT
AL-1607

TO Industrial Hygiene Committee DATE May 4, 1964
Chairmen

SHEET NO. 4


these dusts is quite common. They may also cause asthmatic-like reactions in certain sensitive individuals. (We have already experienced this in our Company.)

Because active components of epoxy resin systems are present in them, dusts from Marinite cannot be treated as mineral dusts. Additional precautions are necessary, and the saw should be equipped with exhaust ventilation. (This is in accord with the recommendations of Johns-Mansville.) Probably most of the fabricating plants will require this type of set up. Respiratory protection is no substitute for exhaust ventilation, except at locations where cutting Marinite is an unusual, infrequent, and brief occurrence.

Sawyers should wear long sleeved shirts to protect their arms from the irritant dust. Personal cleanliness is also important and the men should be instructed to wash up following their exposure to Marinite dust.

If any of the recipients have any specific questions or comments concerning Marinite, we will be pleased to hear from them.

The latest of the Hygienic Guides are enclosed: Acrolein, Aluminum, Ethylene Glycol Monoethyl Ether, Manganese, Petroleum Naphtha, Pyridine, Tetraethyl Lead, Allyl Alcohol, Allyl Chloride, Cyclohexane, Ethyl Chloride, and Triorthocresylphosphate.



Thomas B. Bonney

TBB/mje
Enclosures

cc/encl: Company physicians

G. H. Farrah, J. M. Plunkett, ARL

F. H. Illig, Pgh.

M. O. Colwell, L. V. Cralley, file

APC 004273

5/4/64

Industrial Hygiene Committee Chairmen

K. W. Perry	Bauxite Al.
W. L. Mowe	Mobile
N. W. Nielsen	
F. R. Cauthier	Alcoa Fab
W.V.M. Williams	Alcoa Sm.
N. A. Hayes	Badin
W. S. Barr	Massena
O. L. Royer	Pt. Comf. Sm.
C. O. Turner	Pt. Comf. Ref.
H. A. Semken	Rockdale
E. B. Porter	Vancouver
R. L. Parsons	Warrick
G. D. Bruno	Wenatchee
A. J. Kukla	Chicago
D. J. Levin	Cleveland
W. M. Harris	Cressona
W. C. Harvey	Davenport
W. C. Seipp	Detroit
A. M. Miller	Edgewater
J. W. Foulke	Edison
L. S. Chambers	Lafayette
Arthur Hartwell	Lancaster
C. L. Bissonette	N.K.
R. E. Hospes	Richmond
T. I. McClintock	Vernon

APC 004274

Febr., 1964

Plant Doctors

<u>Division</u>	<u>Works</u>	<u>Doctor</u>
<u>Raw Materials</u>	Bauxite	James Bethel
	Rosiclare	John R. Duffey
<u>Refining</u>	Bauxite	* James Bethel
	Mobile	Howard Walker, Jr.
	Pt. Comfort	John Griffin
<u>Smelting</u>	Alcoa	W. N. Dawson
		J. C. Phelan
	Badin	A. F. Lapsley
		Orville Jack Duncan
	Massena	Maurice J. Elder
	Pt. Comfort	* John Griffin
	Rockdale	J. T. Richards
	Vancouver	F. J. O'Hara
	Warrick	Thomas C. Burger
	Wenatchee	L. C. Miller
<u>Fabricating</u>	Alcoa	* W. N. Dawson
		* J. C. Phelan
	Chillicothe	Charles N. Hoyt
	Cressona	Ralph Lyons
	Davenport	A. W. Shafer
		Frank Stine
	Edgewater	Joseph Ferrante
	Lafayette	No regular plant doctor
	Lancaster	Carl C. Kessler
	Massena	* Maurice J. Elder
	New Kensington	Colin Kamperman
	Richmond	Ralph W. Dreyer
	Vancouver	* Frank Stine
	Rome	J. Mc Donough
<u>Foundry</u>	Chicago	Ralph P. White
	Cleveland	W. A. Engel
	Detroit	A. J. Szmigiel
	Edison	Malcolm Dunham
	Vernon	Victor H. Barbour
<u>ARL</u>	E. St. Louis	W. A. Engel
	New Kensington	D. A. Fusia, Jr.
<u>Alcoa Bldg.</u>	Pittsburgh	W. Leigh Cook, Jr.
		C. E. Anderson
		E. A. Brethauer
		R. McC. Coyte
		Norman Davis
		W. A. Engel

* = duplication

APC 004275