FILE NAME: Chrysler (CHRY)

DATE: 1975 Jan 22

DOC#: CHRY109

DOCUMENT DESCRIPTION: Letter RE OSHA Regulation & Corrective Action Taken - Friction Materials Laboratory Disc Grinder Evaluation

D Zuckerbach

CHEMICAL DIVISION CHRYSLER CORPORATION

January 22, 1975

Dear John Nordman:

The Occupational Safety and Health Act Section 1910.93a (1)(3) requires that an employee be informed of an exposure to asbestos fibers and action taken to correct the condition contributing to the exposures.

This letter is to inform you that laboratory results of personal air samples taken on January 7, 1975 indicates an exposure to airborne asbestos fibers. The exposure resulted from operation of the disc sander.

The corrective action taken is:

a) Remove disc sander feature of machine

In addition, as a precautionary measure, you will be scheduled for a physical examination in the immediate future.

Please contact the Personnel Office for further information relative to your physical examination and on any questions pertaining to this notice.

Sincerely,

J. M. Knoll

J. M. Knoll

Plant # 1602
Dept # 2000
Lab Code 9134

5437 W. JEFFERSON, TRENTON, MICHIGAN 48183

Inter Company Correspondence

File Code: Date: January 22, 1975

Name & Department		Division	Plant/Office	Cl.&S Number
D. P. Glazier	Industrial Hygiene	Personnel	Chrysler Center	417-05-19
From Name & Department		**Division**	**Plant/Office**	**Cl.&S Number**
S. C. Enders	Plant Manager	Chemical	Trenton	453-02-00

Subject: FRICTION MATERIALS LABORATORY DISC GRINDER EVALUATION

The problem of employee exposure to airborne asbestos concentration when using the disc sander in the Friction Products laboratory has been solved by removing the equipment from service permanently.

S. C. Enders

/ph

cc: J. A. Lardie
E. R. Lombard