

BLOOMFIELD SILO CO., INC.

TELEPHONE 612-364-4305, 612-324-4154

620 SOUTH JEFFERSON

BLOOMFIELD, INDIANA 47404

December 19, 1972

Material and Labor used in repairing and rebuilding Bloomfield Silos because of the use of Cumar containing PCB's.

Mr. Walter Ballard, Route 2, Loretto Kentucky 12'x40' Silo; Cleaned walls, refinished inside	\$ 266.20
Mr. Clifford Ard, Route 1, Nancy Kentucky 20'x60' Silo; Taken down and rebuilt with new Concrete Staves.	\$5,025.17
Finis Flynn, Route 1, Nancy Kentucky 20'x60' Silo; Taken down and rebuilt with new Concrete Staves. Also Scraping inside of 20'x60' and refinishing	\$5,025.17 935.00
Mr. Vernon McGowan, Jabez, Kentucky 20'x60' Silo; Taken down and rebuilt with new Concrete Staves	\$5,025.17
Marcus Muse, Route 1, Nancy Kentucky 20'x60' Silo; Taken down and rebuilt back with new Concrete Staves Also Scraping inside a 20'x60' and refinishing	\$5,025.17 935.00
Hollan Shuffett, Route 1 Greensburg, Kentucky 20'x60' Silo; Taken down and rebuilt with new Concrete Staves	\$5,025.17
John DeBoard, Somerset, Kentucky 16'x40' Silo; Scraping walls and refinishing inside. <i>Need floor</i>	\$ 375.00
Donnie Gene Adams, Route 4, Martinsville, Ind. 18'x50' Silo; Walls cleaned and refinished	\$ 434.00
Total	\$28, 071.11

Signed

Mr. Rex Autrey, Vice-President

0512774