bcc: J. F. Stapleton

May 2, 1973

Dr. A. Pozefsky
General Electric Company
Industrial & Power Capacitor
Products Department
John Street
Hudson Falls, New York 12839

Mr. E. L. Raab
General Electric Company
Transformer Division
Building 11-223
100 Woodlawn Avenue
Pittsfield, Massachusetts 01201

Gentlemen:

A recent incident in which askarel fluid in a transformer on its way to the customer was permitted to drain onto farmland dramatically highlights the need for specific instructions that can be made available to private and public carriers to instruct them in the proper handling of askarels during emergency conditions.

I recommend that your two committees jointly consider appropriate guidelines that would apply to this type of situation and which would be included in the ANSI Committee C-107 askarel guidelines.

Sincerely,

W. B. Papageorge
Chairman
ANSI Committee C-107

WBP/bt

cc: Mr. P. B. Beniznus
Steering Committee Chairman
ANSI Committee C-107

Mr. A. M. Salazar, Secretary
Transformer Section
and ANSI C-107

010657

ADM 007664

PLAINTIFF'S EXHIBIT 833

WATER_PCB-00049347