CONOCO CHEMICALS – ABERDEEN PVC PLANT
DOSIMETRY CARD (A)

SAMPLE Nº 1316 A

Hazard: VCM (X) Lead ( ) Noise ( ) _____ ( ) Date July 28-1980

Name Rubin Gates S. S. # 587-66-4044 Shift A

Department Vinyl Job Class A operator

	Start	Stop
Instrument No. 74-R	Time 7 AM( ) PM(✓)	7 AM(✓) PM( )
Noise Cell No. _____	Airflow _____	_____

Analyst: [signature] Analysis Date: 8-1-80

Hazard		TWA Exposure
VCM	PEL: 1 PPM	<0.1 PPM
Noise	Over ( ) Under ( ) 115 dBA	% of PEL
Lead (Micrograms)	TOT: PEL: Per M^3	Per M^3

CONOCO CHEMICALS – ABERDEEN PVC PLANT
DOSIMETRY DATA CARD (B)

SAMPLE Nº 1316 A

Hazard: VCM (X) Lead ( ) Noise ( ) _____ ( ) Date July 28-1980

Time Clock (Lead Sampling Only) : IN: 1900 AM( ) PM(X) OUT 0700 AM(✓) PM( )

List areas you spent most time in and estimate amount of time (nearest hour is sufficient) spent.

Area	Time	Area	Time
Old Unit			
New Unit			

List most likely causes of possible overexposure to the hazard.

1. _____
2. _____
3. _____

Check respiratory protection you used:

(X) None ( ) Dust Mask ( ) Air-line Respirator ( ) Scott Air-pak

Signature Douglas M. Spana

Please complete and return to guard