

COLUMN PERFORMANCE INDICATORS



Calculating Column Efficiency

1. **Theoretical Plates, N**

$$N = 16(x/y)^2$$



Calculating the Tailing Factor

2. **Tailing, T**

$$T = a/2b$$

0071076

TOWOLDMON0056873