CG TB CODE RW-768-P PKG 93 ( )RW-768-P (K) APPROVED BY BBK 11/5/81 JJG 06/11/82

12/27/82 (DATE) L2H59-1 (LOT) 12,538 ~~10,467~~ [redacted] LBS (EST WGT) 12,408 / 12,538 x 100 = 99.0% #3 P.M. COMTYP JOB NAME: 16RW768PMK

LOCATN	CG	CODE	PQ	LOT	DRY* WEIGHT	DRY CONT	NO. PKG	PKG WGT	TOTAL WEIGHT	ACTUAL USE LBS
	16	RW-768-P	93	E2K30-2	—	—			120	120
	16	RW-768-P	93	J2K37-1	—	—			23	23
	16	RW-768-P	93	D2H02-1	—	—			7650	7650
	16	RW-768-P	93	M1579-2	—	—			4800	4800
	16	RW-768-P			—	—				

Note Do Not use Alm (Reg. No. 11018)

EQUIP MENT		NAME: MONASTRAL RED B 2 PAGES	USE LBS	N-CODE	ACCT LBS
MISC 1		NOTE: MAKING SUPV - 1 HR BEFORE TAKING S24 & S34 SAMPLE, ADVISE CTL OF STATUS			
	1	OBTAIN AS LISTED ABOVE		RW-768	12,596
		[redacted]			
320 2		CLOSE V-320 OUTLET VALVE			
		PUMP RW-768 FROM S1 INTO V-320			
		NOTE: STIR TOTES & DRUMS TO INCORPORATE ANY settled SOLID PRIOR TO OR WHILE PUMPING			
	10	STIR 30 MIN			
	11	STOP AGITATOR			
	12	RECORD: PH 10.0 (10.0-12.0)			
	13	IF NECESSARY, ADJ TO PH (10.0-12.0)			
		ASSUME 50%		7-D	
		RECORD PH_____ ASSUME 70%		30-D	
	14	POUR IN	65	195-B	65
	15	STIR 10 MIN			
		[redacted]		[redacted]	
		~~DURING HOMOG.~~			
		PROCEED to S23 2nd page		NOV 1 1982	
		[redacted]			

10/29

EQUIP MENT		PAGE 2 OF 2 CG 16 CODE RW-768-P (K)	USE LBS	N-CODE	ACCT LBS
CV 3 CONT	[redacted]				
	23	REMOVE DISCHARGE LINE & SCREEN			
	24	WHILE DISCHARGING HALF OF A 6 GAL. KIT THRU THE BOTTOM OUTLET, SET FLOW TO ENABLE FILLING A JAR (REFER TO PROCEDURE M0012). FILL 1-16 OUNCE JAR. DELIVER TO CTL FOR COLOR. RECORD: S-38 & SHUT OFF AGITATOR, LIGHTS AND CLOSE MANHOLE COVER.			
[redacted]					
CV 5	26	ADD _____# WATER AS REQUIRED TO CV NOTE:IF TEST IS SATSFCTRY, OMIT S'S 26-29			
	27	START AGITATOR & STIR 20 MIN OR LONGER TO UNIFORMITY.			
	28	FILL 1-16 OUNCE JAR AS PER S-24 & DELIVER TO CTL FOR COLOR. RECORD: S-38.			
	29	SHUT OFF AGITATOR UNTIL TEST IS AVAILABLE			
	30	WHEN TEST SATISFACTORY, START AGITATOR, STIR 20 MIN OR LONGER			
	31	CHECK PAKOUT SCALE ACCURACY: 50# _____ 500#_____			
	32	INSTALL PACKOUT LINE & SCREEN (MAKE SURE IT'S CLEAN)			
	33	AFTER DISCHARGING +/-25 GAL, FILL 2-16 OZ. JARS FROM PACKOUT LINE & RUN SCREEN TEST AS PER PROCEDURE M0026 WITH 1 JAR.			
	34	IF SCREEN TEST OK, DELIVER 1-16 OZ JAR TO CTL FOR SCREEN TEST. RECORD TIME:_____ NOTE: OPERATOR SHOULD WAIT FOR RESULTS.			
	35	IF SCREEN TEST IS OK, IMMEDIATELY BEGIN DISCHARGING THRU PAKOUT SCREEN AS FOLLOWS: ,RECORD: S-38 PKG N-CODE: 6 Gal Kits — SCHEDULE PK: ± 249 — TOTAL NET PK: ~~12,467~~ 12,408			
	36	AFTER DISCHARGING +/- 80% OF BATCH, FILL COMPLETELY 2-16 OZ. JARS FROM PAKOUT LINE, MARK "FINAL", DELIVR TO CTL FOR COLOR TEST WHEN PAKOUT COMPLETE, RECORD: S38			
	37	STOP AGITATOR			
	38	RECORD: RESULTS TIME SUPV S24 SMPL TO CTL-CLR _____ _____ ____ S28 RESMPL TO CTL-CLR _____ _____ ____ S33 AREA SCREEN TEST _____ _____ ____ S34 SMPL CTL SCRN TEST_____ _____ ____ S36 FNL SMP CTL-CLR _____ _____ ____ START: 9:30 R — FINISH: 11:00 R — OPTR: 27			

* * * * * * * * *

DUP050060442