bag of the arcing machine shall be removed and replaced with the hose of the high efficiency industrial vacuum described above.

4 All floor cleaning in areas, where brakes and clutches are repaired should be done with the high efficiency industrial vacuum cleaner as described above. Grinding (arcing) machines should also be cleaned with such a vacuum cleaner and any remaining dust wiped with a damp cloth. An approved respirator as described above, should be used during this cleaning.

In addition to those measures NIOSH also recommends the following procedures:

5 If possible, an area should be designated for all brake and clutch repairs. Entrances into this area should be posted with an asbestos exposure warning sign as follows:

Asbestos
Dust Hazard
Avoid Breathing Dust
Wear Assigned Protective Equipment
Do Not Remain in Area
Unless Your Work Requires It
Breathing Asbestos Dust May Cause
Asbestosis and Cancer

6 Industrial vacuum cleaner bags containing asbestos dust and cloths used for wiping brake and clutch assemblies should be sealed in plastic bags and labeled with the following warning label printed in letters of sufficient size and contrast to be readily visible and legible:

Caution
Contains Asbestos Fibers
Avoid Breathing Dust
Breathing Asbestos Dust May Cause
Asbestosis and Cancer

During removal of vacuum bags an approved respirator, as described above, should be worn.

7 Although adherence to the above procedures should minimize any contamination of work clothing, it is recommended that the appropriate portions of the OSHA regulations on asbestos ~~(29 CFR 1910 1001 (d) (3) and (4))~~ concerning special clothing, change rooms, etc. be followed. These call for special clothing including coveralls, head covering, gloves and foot covering to be provided, along with separate lockers for work clothes and street clothes. They also specify a change room, transportation of contaminated clothing in sealed labeled bags to the laundry, and notification of the laundry that the clothing is contaminated with asbestos.

8004 1812