PLAINTIFF'S EXHIBIT
MON-3118

Monsanto

George Orum, Texas City, Texas

May 25, 1978

Face Mask Requirements
By Craft

cc Craft Foremen
N. J. Broussard
Paul Siems
C. M. McCullough

TO : Leonard Schwab

Craftsmen are subject at any time to be required to wear the respiratory equipment as listed below. All must be able to wear the equipment specified for each craft and have the face mask seal appropriatly without impingement by facial hair.

PIPEFITTERS

Full face fresh air mask.
Half face fresh air mask.

BOILERMAKERS

Full face fresh air mask
Half face fresh air mask

MACHINIST

Full face fresh air mask
Half face fresh air mask.

INSULATORS

Full face fresh air mask
Half face fresh air mask
Comfo II dust respirator

CARPENTERS

Full face fresh air mask
Half face fresh air mask

PAINTERS

Airfed hoods (beards no problem)
Comfo II respirator

OPERATING ENGINEERS

Comfo II dust respirator
Escape mask

TRUCK DRIVERS

None ???

LABORERS

Full face fresh air mask
Half face fresh air mask
Comfo II dust respirator

George Orum

George Orum

rms

MAP 001395

LAM023271