

FILE NAME: Hopeman Brothers (HB)

DATE: 1970 Dec 21

DOC#: HB006

DOCUMENT DESCRIPTION: Teletype Message with Response



12/21/79

DATE

TELETYPE MESSAGE

DO NOT WRITE OR TYPE IN THIS SPACE

B.1 B/C 1/4

To:	BIL	S. SWIACKY
	LOCATION	NAME

DID WE GO THROUGH SOME MARINITE AND REMOVE HAZARDOUS PRODUCTS LABELS? IF SO
 HOW DID THEY COME OFF? IF NOT, HOW ABOUT GLUING A BOTTOM PALLET THAT HAS BEEN
 AROUND FOR AWHILE AND TRY TO REMOVE LABEL. IN TALKING WITH COGGINS ^{NO} ONE IN
 JH HAS HAD A FIRST HAND LOOK AT LABEL STICKING PROBLEM. WE DO NOT KNOW ^{EXTENT} OF
 PROBLEM. HOWEVER IN ~~WY~~ HOPEMAN'S CASE IT IS IMMATERIAL WHETHER THE PROBLEM IS REAL
 OR IMAGINARY. HOPEMAN WILL NOT ACCEPT PRODUCT WITH LABELS. PERIOD. WEBER HAS
 ADVISED INDUSTRIAL ACCOUNTS MUST STILL HAVE NEW COMBINATION ~~PRACY~~ PRODUCT AND
 CAUTION LABEL ON THEM. EXAMPLE OF THIS LABEL IS MARINITE 36 USING LABEL #LIN-557
 HAVE REVIEWED THIS WITH WINGERTER.

PRINT OR TYPE - BE BRIEF.

WHY FILE THIS!

D. S. FISCHER
 SENDER

T-03003
 12/21/79
 RESP. NO.




#V
 MANJM
 .BILJMJM 12/21
 D S FISCHER



WIRE

WENT THRU LOAD OF 2" 10 FT MTE 36 MAIL ON BOTTOM PALLET
 HAD BEEN IN INVENTORY SINCE 9/29 HAZARDOUX LABELS WERE REMOVABLE
 WITHOUT TEARING LABEL SURFACE OF PANELS WAS RELATIVELY DUST FREE
 ALSO SURFACE HARD PANDUX EXCEEDED 55 UNITS ALSO REMOVED LABELS FROM
 MTE 65 ALSO REMOVABLE IN ONE PIECE



SWIACKY

Handwritten: When removed also Swiacki

Handwritten: Holm Long

MT-000008