


011 0111111111 0 111

Intracompany memo

to Mr. T. E. Withycombe
Mr. A. T. Niebergall
from O. E. Burch
subject CAUTION LABELS



location Portland
location Portland
location Portland
date June 6, 1974

I am attaching copies of our new Caution Labels for your files.

EXHIBIT #1:

These will be printed on our one gallon and five gallon Ready-Mix cans. We have also ordered a supply of stickers for each of our plants to be used until printed cans are available.

EXHIBIT #2:

Our present bags have a Caution Label printed on them which complies with OSHA requirements. New bags will have the attached label printed on them which exceeds OSHA requirements.

OEB/mf

O.E.B.

CC Messrs: G. E. Wilson, Portland
J. Hurd, Portland
C. W. Lehnert, Tigard Lab
T. W. Richards, Tigard Lab
E. B. Hollingsworth, Wilm Del Gyp
D. C. Corkill, Portland

encl.

RECEIVED
JUN 07 1974

SGP 0007589

5 gal Ready-Mix

- CONTAINS ASBESTOS FIBERS.
- AVOID CREATING DUST.
- BREATHING ASBESTOS DUST MAY CAUSE SERIOUS BODILY HARM.
- USE APPROVED RESPIRATOR WHEN SANDING.

1971 Ready Mix

- CONTAINS ASBESTOS FIBERS.
- AVOID CREATING DUST.
- BREATHING ASBESTOS DUST MAY CAUSE SERIOUS BODILY HARM.
- USE APPROVED RESPIRATOR WHEN SANDING.

五、四、三、二、一

Ben Jones

- CONTAINS ASBESTOS FIBERS.
- AVOID CREATING DUST.
- BREATHING ASBESTOS DUST MAY CAUSE SERIOUS BODILY HARM.
- WHEN MIXING OR SANDING USE APPROVED RESPIRATOR.

11