

- 2 -

General:

9. The exhaust of Torit Dust Collector in the ball joint area was connected to ducts that conveyed the lead particles out of the plant.
10. In the final analysis, an excellent dust control program is in operation except in specific areas where improvement is required.