Δ 68

[illegible]

intracompany memo

to	Mr. T. E. Withycombe Mr. A. T. Niebergall	location	Portland Portland
from	O. E. Burch	location	Portland
subject	CAUTION LABELS	date	June 6, 1974

I am attaching copies of our new Caution Labels for your files.

EXHIBIT #1:
These will be printed on our one gallon and five gallon Ready-Mix cans. We have also ordered a supply of stickers for each of our plants to be used until printed cans are available.

EXHIBIT #2:
Our present bags have a Caution Label printed on them which complies with OSHA requirements. New bags will have the attached label printed on them which exceeds OSHA requirements.

OEB/mf

O.E.B.

CC Messrs: C. E. Wilson, Portland
J. Hurd, Portland
C. W. Lehnert, Tigard Lab — THIS COPY FOR
T. W. Richards, Tigard Lab
E. B. Hollingsworth, Wilm Del Gyp
D. C. Corkill, Portland

encl.

RECEIVED
JUN 07 1974

EXHIBIT
PENGAD 800-631-6989
L
Schutte
2-15-13

EXHIBIT 1

5 GAL. READY-MIX

CAUTION

- CONTAINS ASBESTOS FIBERS.
- AVOID CREATING DUST.
- BREATHING ASBESTOS DUST MAY CAUSE SERICUS BODILY HARM.
- USE APPROVED RESPIRATOR WHEN SANDING.

1 GAL READY MIX

CAUTION

- CONTAINS ASBESTOS FIBERS.
- AVOID CREATING DUST.
- BREATHING ASBESTOS DUST MAY CAUSE SERIOUS BODILY HARM.
- USE APPROVED RESPIRATOR WHEN SANDING.

EXHIBIT 2

BAR GOOD

CAUTION

- CONTAINS ASBESTOS FIBERS.
- AVOID CREATING DUST.
- BREATHING ASBESTOS DUST MAY CAUSE SERIOUS BODILY HARM.
- WHEN MIXING OR SANDING USE APROVED RESPIRATOR.