

The suppliers of clutch plates and bands for automatic transmissions since 1964 have been Raymark and Spring-Brummer Division of Borg-Warner Corporation. The suppliers of bands since 1964 have been Spring-Brummer Division or Borg-Warner Corporation and D.A.B Industries. Suppliers of clutch plates are Sheepbridge, Raybestos, Manhattan, Raymark, S.K.Wellman, Thermoset, Borg Warner, and Delco Moraine.

Suppliers of clutch plates for manual transmissions facings were (dates are approximate):

Raymark Industrial Division Southfield, MI	1965 - 1985
H. K. Porter Troy, Michigan	1965 - 1971
Sources of assemblies were (dates approximate):	
Borg Warner Corporation Chicago, Ill.	1930 - 1985
Borg & Beck Sterling Heights, MI	1974 - 1984
LUK, Inc. Southfield, MI	1983 - 1985
Alma Products Co. Alma, MI	1974-1985
Daikin (Asahi facings) Troy, MI	Unknown

GM purchased friction materials that it used on clutch plates discs from other companies that were not manufactured by GM. Some of these clutch plates or discs contained asbestos and others did not. GM's understanding of the industry practice is that chrysotile was best suited for and used