FILE NAME: Powhatan (PHN)

DATE: 1968

DOC#: PHN020

DOCUMENT DESCRIPTION: Govt Inspection Reports

DIVISION OF OCCUPATIONAL HEALTH
INVESTIGATION OR SERVICE

Date 10/10/68	P.H. Engineer WRM	Man Visits 1
Plant Powhatan Mining Co.		Code No. Co. 03
Address 6721 Windsor Mill Rd. Woodlawn		Employees M 7 F 0 T 7

PURPOSE	REASON	PERSON TO RECEIVE REPORT
1 ___ Survey	1 ✓ Self Initiated	Miss Frances Metf
2 ✓ Reinspection	2 ___ O.D. Report	PERSONS INTERVIEWED
3 ___ Investigation	Complaint - Request	Mr. Roland M. Schisler
4 ___ Study	3 ___ Management	
5 ___ Follow-Up	4 ___ Labor	
6 ___ Consultation	5 ___ Neighbors	
7 ___ Special Activities	6 ___ Health Office	
8 ___ Project Activities	7 ___ Other	

RECOMMENDATIONS REGARDING ENVIRONMENTAL PROBLEMS

New Problems	Requested Improvement	Code	Persons
None.			

Past Problems Completed	Requested Improvement	Code	Persons
None			
Not Completed 0			

Field Studies	Remarks	Code	Persons
None			

Samples submitted for analysis — No. 0

Memo ✓ | Plant Record | ~~Letter/Report~~ no copies | Next Visit Reviewed 4/71

Powhatan Mining Co.
6721 Windsor Mill Road
(1 block south, road east of 6721)
Woodlawn

Reinspection

Mr. Roland M. Schisler, Foreman, was interviewed.
Former Superintendent, Mr. Earl Smith, no longer with company.
Mr. Fred A. Mett, former owner, has died. His sister, Miss Frances Mett is current owner and addressee for correspondence. (Residence and office adjacent at 6721 Windsor Mill Road.)

No change in asbestos grinding (3 HAZEMAG impact mills # 10, # 20, # 30) and purifying (muriatic acid, cooking, washing, pressing, drying, screening) as described trip memo 11/1/65.

No recommendations:

WRM:ml 10/25/68