

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	04/06/2023	Time	10:30
Inspection Due		Operator Representative	CEP Mid-Continent, LLC		
Operator Info	CEP Mid-Continent, LLC 1560 E. 21st Street, Suite 215 Tulsa, OK 74114 Phone: 918-281-5274	Inventory ID	OS5307000		
		API Well No			
		Lease Name	O.I.R		
		Well ID	8		
Location	SE 19 22N 12E	Status	Inactive	Well Type	Disposal
Latitude	36.363129	Longitude	-96.052573		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	CEP Mid-Continent, LLC		
Inspect No.		Date Last MIT	07/20/2022	Last Test Result	F
Casing	7	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 150
FLM Canister Pressure		Actual Pressure	0		Max Volume 24000
Lease Status	Inactive	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Speedy Well Service (SWS) place cement bottom plug in well OS5307000. Inspector observed SWS run in hole to 2333 feet below the land surface, then pump 25 sacks of class A cement. SWS pulled out of the well and moved off the well with a plan to return on 4/11/2023 to tag the top of cement and place the cement top plug. Inspector observed no areas of concern at the time of the bottom plug placement.				
Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2023.05.03 16:04:00 -05'00'				
Supervisor Signature	DAMON MCELROY Digitally signed by DAMON MCELROY DN: c=US, o=U.S. Government, ou=Environmental Protection Agency, cn=DAMON MCELROY, 0.9.2342.19200300.100.1.1=68001003655653 Date: 2023.05.03 21:43:28 -05'00'				