

Out-Remove from Stores  
Stock

TABLE

ASBESTOS RELATED PROBLEMS, COMMENTS, AND SUGGESTED SOLUTIONS

| ITEM | DESCRIPTION                   | COMMENTS                             | SUGGESTED SOLUTIONS                                                                |
|------|-------------------------------|--------------------------------------|------------------------------------------------------------------------------------|
| a.   | Asphalt Mastic                | No problem unless sprayed            | Do not spray                                                                       |
| b.   | Braided Packing               | Contained, considered safe to handle | Personnel monitoring to verify claim                                               |
| c.   | Asbestos Gloves               | Probable source of exposure          | Personnel monitoring. Look for substitute                                          |
| d.   | Heat Suits                    | Same as f.c.                         | Look to aluminized "Nomex" as substitute                                           |
| e.   | Hot Pads                      | Same as f.c.                         | Same as f.c.                                                                       |
| f.   | Insulation                    | Separate listing                     | See Item 2                                                                         |
| g.   | Molded packing                | Contained, no problem                | None required                                                                      |
| h.   | Sheet gasketing               | Contained, no problem                | None required                                                                      |
| i.   | Calcium Silicate              | Probable source of high exposure     | Personnel monitoring to verify claim. Look for substitute material.                |
| j.   | Inhibited Calcium Silicate    | Same as 2.a.                         | Same as 2.a.                                                                       |
| k.   | Kaylo 20                      | Same as 2.a.                         | Same as 2.a.                                                                       |
| l.   | Asbestos Board                | Problem when saved                   | Same as 2.a.                                                                       |
| m.   | Asbestos Roofing Felt         | Contained, no problem                | None required                                                                      |
| n.   | Fibrated asphalt Emulsion     | No problem unless sprayed            | Do not spray                                                                       |
| o.   | Fibrated asphalt Cut-back     | Same as 2.f.                         | Same as 2.f.                                                                       |
| p.   | Asbestos Cloth (listing tape) | Possible source of high exposure     | Personnel monitoring to verify claim. Evaluate J-M Thermo-chem tape as substitute. |

DUP 0900982

135

121311

1-B-7A

Asbestos  
1992

# ASBESTOS RELATED PROBLEMS, COMMENTS AND SUGGESTED SOLUTIONS

| ITEM | DESCRIPTION                              | COMMENTS                         | SUGGESTED SOLUTIONS                                                                  |
|------|------------------------------------------|----------------------------------|--------------------------------------------------------------------------------------|
| i.   | Asbestos cloth (insulation fittings)     | Same 2.h.                        | Same as 2.h.                                                                         |
| j.   | Fire resistive Fibrated Asphalt Cut-back | Same as 2.f.                     | Same as 2.f.                                                                         |
| k.   | Fibrated Asphalt Dispersion              | Same as 2.f.                     | Same as 2.f.                                                                         |
| l.   | Asbestos paper                           | Probably safe to handle          | Personnel monitoring to verify claim                                                 |
| m.   | Flexible Braided Asbestos Tubing         | Possible Source of high exposure | Personnel monitoring to verify claim                                                 |
| n.   | "Tedlar" Neoprene Asbestos Laminate      | Probably safe to handle          | Same as 2.l.                                                                         |
|      | "Hypalon" Neoprene Asbestos Laminate     | Same as 2.l.                     | Same as 2.l.                                                                         |
| p.   | Fibrous Adhesive                         | Contained, no problem            | None required                                                                        |
| .a.  | Insulation Storage                       | Possible source of high exposure | Thorough vacuum cleaning, repeat periodically. Personnel monitoring to verify claim. |
| .a.  | Dismantling                              | Possible source of high exposure | Soak with water. Personnel monitoring                                                |
| b.   | Installing Calcium Silicate Insulation   | Probable source of high exposure | Personnel monitoring. Substitute as quickly as possible.                             |
| c.   | Waste Disposal                           | Regulated by OSHA                | Follow 37 FR 11321 Part 1910.93a h.2.                                                |

DUP 0900983

4-B-75  
JUL 9 1992

JUL 9 1992

121312