

MICHIGAN DEPARTMENT OF HEALTH

ALBERT E. HEUSTIS, M.D., State Health Commissioner

LANSING, MICHIGAN 48906

TELEPHONE 575-1657

575-1500 HOURS: Sat., Sun., & HOLIDAYS



STATE OF MICHIGAN
GEORGE ROMNEY
Governor

July 2, 1965

Reply to: Wayne County Department of Health
Eloise, Michigan

Chrysler Corporation
Chrysler Chemical Division
5437 W. Jefferson
Trenton, Michigan

Attention: S. B. Twiss, Ph.D., President

Gentlemen:

On May 19, 1965, we conducted a study of the various operations handling asbestos and toluene to determine whether your employees were being exposed to concentrations above our limits.

Air samples were collected in the breathing zone of the workers loading raw asbestos into the mixers and after various machining operations. In general the dust found in the samples was below the established limit. One of the samples collected at No. 3 Saw was slightly above the limit indicating that the ventilation and hooding should be checked to see if it is operating at maximum efficiency.

Solvent samples were collected in the breathing zone of the workers during the emptying of the mixer and the loading of the portable boxes, the shoveling of the mix into the extrusion press and stacking the extruded linings on the drying racks. The air samples collected indicated high concentrations during the emptying of the mixer and the shoveling of the mixed material from the portable box into the extruder. The concentration in the mix room was of short duration and did not appear significant compared to the time of exposure and the background concentration of 10 to 20 parts per million. However the shoveling of material occurs over a longer period of time and is a problem. The average concentration during the shoveling operation is 250 parts per million with the peak concentration exceeding this figure. The ventilation on the box was checked and found to be approximately 100 cubic feet of air per minute, very low according to our standards for good ventilation.

EXHIBIT

CHR-71

RECEIVED

JUL 22 1965

S. B. TWISS
CHEMICAL DIV.

Chrysler Corporation
Chrysler Chemical Division
July 2, 1965
Page 2

Some type of corrective measures should be initiated at the shovelling of brake lining material into the extruder hopper--one, either change the method of loading the extruder to reduce the employee exposure or two, increase the exhaust ventilation to 1750 cubic feet of air per minute per box.

We are enclosing the data collected during our study and if there are any questions before our next visit please feel free to contact us.

Very truly yours,

DIVISION OF OCCUPATIONAL HEALTH



Marvin M. Schuman
District Engineer

MS/ja

Enclosure

cc: Donald Eschelbach, Industrial Hygienists