


FIG 25-30 – Mechanical methods for stripping finished pieces from power press dies