PLAINTIFF'S EXHIBIT USM-316

RESEARCH PROJECT

No. 11

Title Dustless Patching Formula

File N. C-P-3

Date

Requested by Frank M. Stumpf

Remarks

Develop dustless patching formula so that the dustless method will not be necessary for use with the patching equipment

---

Since the Asbestos contains most of the dust; this is the start.

A- Study sieve analysis to determine type screen required to decrease dust

B - Sieve Analysis in 6, 12, 30, 50, Pan Sieves and determine dust on dust tester

C- Rotate larger quantity in rotary screen

D - Blow fiber through blower and catch heavier fibers

E - Spray oil onto fibers

The most suitable of the above to be mixed in a Cafco formula and tried with the patching equipment

Stumpf Ex 188