



INTERNAL
CORRESPONDENCE

PLAINTIFF'S EXHIBIT

UC-2767

UNION CARBIDE CORPORATION TECHNICAL CENTER
P.O. BOX 8361, SOUTH CHARLESTON, WV 25303

To: F. Sunderland	Date: April 18, 1986
From:	Originating Dept: HS&EA
Subject:	Area: Industrial Hygiene
Re: B. H. Avashia, M.D. J. H. Barna W. L. Browning M. R. Gandee C. P. Maxwell B. R. McMakin	Subject: <u>Asbestos Exposure Monitoring</u>

Attached are the results of the Asbestos monitoring performed on two insulators and one laborer just outside Building 9 at the Institute plant. There were four insulators and three laborers working on this job, stripping approximately 100 ft of 6 inch line.


All employees were equipped with disposable coveralls, headsock, boots, gloves and a cartridge respirator designed for dusts and mists. The disposable equipment was discarded before leaving the barricaded area and new equipment worn upon returning. The area was well posted for the Asbestos hazards.


The sample results indicate that all of the exposure levels were below the permissible level of 2 fibers per cc of air. However, we continue to stress the importance of the required usage of excess water to control the airborne fibers and personal protective equipment.

Please inform all employees of their exposure results and if we can be of further assistance, please feel free to call us on extension 4779 or 3750.

WORK BY:

APPROVED BY:


Vance E. Stover


Manhar A. Patel

Attachment

VES:MAP:rab
1220P

UCC 024763

AUDIT REPORT NO. 100078

FILE NO. 14

A T T E N T I O N

This document has been identified as one which may relate to the manufacture, use, sale or health effects of asbestos or asbestos-containing products in connection with Union Carbide's defense of asbestos litigation. The document may be reproduced as needed, but should not be destroyed. If it is judged to be of no further value to this file, the document should be sent to the Danbury office, attention of S. D. Conner. The File No. and Audit Report No. must accompany the document

Likewise, if the address of the document is changed, S. D. Conner should be notified. The File No. and Audit Report No. must be included in the correspondence.

SPCLM .fgr .qmcD

2012382A 38U209X3 2012382A

STNEMMOC	gAWT cc\tradi? cc\tradi?	.qmcD r?A cc\tradi?	gnlfqmc2 emit	gnbfvrf?H .J .R gnmH	gtag
gnlfw bntcelffoz - glqmc2 fanozr99 d to f99t 00f mor? zotz9d99 gnlfqfrz99 .gnlf nclnt	509.0	372.0	nfm 82 9nd d	gnbfvrf?H .J .R	08-01-4
gnlfw bntcelffoz - glqmc2 fanozr99 d to f99t 00f mor? zotz9d99 gnlfqfrz99 .gnlf nclnt	512.0	192.0	nfm 02 9nd d	gnbfvrf?H .J .R	08-01-4
gnlfw bntcelffoz - glqmc2 fanozr99 gnlfqfrz99 zotz9d99 9nd qu gnlfz99 gnlfqfrz99 bnt zotz9d99 9nd .f99z9d99	912.0	572.0	nfm 52 9nd d	gnbfvrf?H .J .R	08-01-4

2012382A 38U209X3 glfdrz99
gAWT
AH20 cc\tradi? S
cc\tradi? 01 gnlfz99

90557