FILE NAME: Superior Combustion Industries (SCI)

DATE: 0000

DOC#: SCI001

DOCUMENT DESCRIPTION: BC Notes

Superior Combustion Industries

- 1961 plant punch card with Operation/Hazard/Control Measure matrix
- 1971 field report plans for installation of ventilation booth and airline respirator use: engineer handling safety will be cut due to poor business
- 1970 Field Report documents use of asbestos for insulation and exposure to workers
- 1965 Field Report with Operation/Hazard/Control Measure matrix with asbestos sawing as an operation. Control measure : "Wet Method"