
FILE NAME: Johns-Manville (JMA)

DATE: 0000

DOC#: JMA409

DOCUMENT DESCRIPTION: Warning Label


CAUTION
Do not use power saws to cut this pipe. Breathing dust created by improper work practices may cause serious bodily harm. When cutting, machining or tapping, refer to the recommended work practice guide furnished to your employer.
AVISO
No use herramientas automaticas para cortar tuberia. Respirar el polvo producido por cortar con herramientas automaticas puede traer consecuencias graves a la salud. Consulte la information suministrada por su supervisor antes de cortar, formar o roscar el material.