FILE NAME: General Electric (GE)

DATE: 1976 Apr 14

DOC#: GE015

DOCUMENT DESCRIPTION: Letter from Johns-Manville to GE

11397

BD

# Johns-Manville Corporation

Greenwood Plaza
Denver, Colorado 80217

Health, Safety & Environment Department

April 14, 1976

Mr. F. L. Teuscher
Design Engineering
Industry Control Department
General Electric Company
1501 Roanoke Blvd.
Salem, VA 24153

Dear Mr. Teuscher:

I have been asked to reply to your letter of March 24, 1976 concerning the fabrication of our TV BORD from the standpoint of the generation of airborne asbestos dust.

Our investigations, including experimental runs we have made and observations of operations in our customers' plants, have shown that the variables in a punch press operation such as feed rate, size, thickness and number of pieces being produced have a great effect on dust generation. Variations in dust counts from different operations are so great that no generalizations can be made. The only way to determine whether or not a TV BORD punching operation meets OSHA exposure limits is to monitor using their prescribed procedure.

Please contact me directly in Denver if you wish to discuss this problem in more detail.

Very truly yours,

Edmund M. Fenner

Edmund M. Fenner, Director
Environmental Services
Vice President, Johns-Manville
Sales Corporation

EMF:jh

bcc Al Moore - 484

T88 1700