Side shields, 16
Signal devices on hoists, 41
Signs, "Keep Out", 40
  near ladders, 35
  for welding, 43
Site areas, work requirements, 18, 19
Slab excavation, 20
Slag, welding, 41-42
Smoking, 9
Softeners in rigging equipment, 33
Solvents, cleaning, 11
Spark catcher, 41-42
Sparking equipment permits, 19
Sparks from welding, 41
Speed limits, 5, 45
Spills, 11-13
  hazardous chemicals, 29
Sprockets, guarding, 41
Stability control, 27
Starter replacement, 24, 25
Steel erection, 33
Stepladders, 36

Storage
  of equipment, 13
  of gas cylinders, 43
  of material, 10, 13
  of petroleum products, 12
Storm sewers, waste disposal in, 30
Straight ladders, 36
Subcontractors, 4
Substation feeders, grounding, 25
Sunday admission to site, 5
Supervisor, contract, 3
Supplies
  delivery of, 10
  removal from site, 10

Suspension scaffolds, 34
Swinging stages, 38
Switch boxes, 23
Switches
  cord, feed-through of, 23
  disconnect, access to, 27
Switchgear fuses, grounding, 25
Synthetic rope, 33

Tag
  contaminated and hazardous equipment
  release, 20, 28
  lockout, 21, 22
Tag lines, 26
Tanks
  storage, 29
  welding in, 43, 44
  work in, 30-31. *See also* Confined spaces
Tar, hot, eye protection for, 17
Telephone, 8
Termination of contract, 2
Testing
  safety, 14, 15
  voltages, 25
Thawing, excavation and, 28
Toeboards on scaffolds, 37
Toes, protection of, 17-18
Toilet facilities, 8

Tools
  hand, 31
  pneumatic, 44
  power, 31, 32
    eye protection for, 17
  responsibility for, 13
  rigging equipment, 33
  sparking, permits for, 19
  storage of, 13

DUP 0911065