FILE NAME: Reddaway Manufacturing (REDD)

DATE: 0000

DOC#: REDD009


DOCUMENT DESCRIPTION: Product Warning Labels

REDDAWAY MANUFACTURING CO., INC. 32 EUCLID AVENUE, NEWARK, NEW JERSEY 07105, U.S.A. (201) 589-1410 FAX # (201) 589-8223

PROCESS AND PROCEDURE FOR PACKING USING BURLAP

Step #1:

Using the 5/8" thick metal strapping place one strap on each end as shown in the picture below. The maximum height of a bale (be it 13's or cut sizes) should be no higher than 52".





REDDAWAY MANUFACTURING CO., INC. 32 EUCLID AVENUE, NEWARK, NEW JERSEY 07105, U.S.A. (201) 589-1410 FAX # (201) 589-8223

Step #2:

Cut a piece of craft paper large enough to cover the rolls you have strapped together. Then place the paper on the floor and wrap the brake lining as shown below.



REDDAWAY MANUFACTURING CO., INC. 32 EUCLID AVENUE, NEWARK, NEW JERSEY 07105, U.S.A. (201) 589-1410 FAX # (201) 589-8223

Step #3:

Using the proper size burlap, pull it over the strapped roll. Then knock the strapped rolls to the floor so you can tie the bottom of the burlap bag with the metal twist, as shown below.




Burlap sizes for material:

Burlap #40	-	1/8" - 5/32" - 3/16" - 1/4" and all Ebony sizes
Burlap #48	-	5/16"
Burlap #60	-	3/8" - 1/2" - 5/8" - 3/4" - 7/8" - 1" - 1-1/8"

REDDAWAY MANUFACTURING CO., INC. 32 EUCLID AVENUE, NEWARK, NEW JERSEY 07105, U.S.A. (201) 589-1410 FAX # (201) 589-8223


Step #4:


Lift the untied end of the bale so it is standing again. Pull the burlap up so you can tighten it. After the burlap is snug, use a metal twist to tie the top of the burlap. Then cut the burlap about 6" away from the bale. The burlap bag is now complete as shown below.





Step #5:

Put a fiberglass label on the bale with glue. Then sew the proper bale tag on. Weigh the bale on the scale. Then using a thick marker, write the weight on the bale.


CAUTION
CONTAINS ASBESTOS FIBRES.
AVOID CREATING DUST.
BREATHING ASBESTOS DUST
MAY CAUSE
SERIOUS BODILY HARM.
CAUTION
CONTAINS ASBESTOS FIBRES.
AVOID CREATING DUST.
BREATHING ASBESTOS DUST
MAY CAUSE
SERIOUS BODILY HARM.
EXHIBIT
tabbies
7
4-13-12



CAUTION
CONTAINS ASBESTOS FIBRES.
AVOID CREATING DUST.
BREATHING ASBESTOS DUST
MAY CAUSE
SERIOUS BODILY HARM.
CAUTION
CONTAINS ASBESTOS FIBRES.
AVOID CREATING DUST.
BREATHING ASBESTOS DUST
MAY CAUSE
SERIOUS BODILY HARM.
DEPOSITION
EXHIBIT
4
WALKER
date?
of first
use of
OSHA
reg many
unlabel




EXHIBIT
tabbies
15
11-13-17

CAUTION

CONTAINS ASBESTOS FIBERS
AVOID BREATHING DUST
BREATHING ASBESTOS DUST MAY CAUSE
SERIOUS BODILY HARM


CAUTION
CONTAINS ASBESTOS FIBRES.
AVOID CREATING DUST.
BREATHING ASBESTOS DUST
MAY CAUSE
SERIOUS BODILY HARM.
CAUTION
CONTAINS ASBESTOS FIBRES.
AVOID CREATING DUST.
BREATHING ASBESTOS DUST
MAY CAUSE
SERIOUS BODILY HARM.
CAUTION
CONTAINS ASBESTOS FIBRES.
AVOID CREATING DUST.
BREATHING ASBESTOS DUST
MAY CAUSE
SERIOUS BODILY HARM.
CAUTION
CONTAINS ASBESTOS FIBRES.
AVOID CREATING DUST.
BREATHING ASBESTOS DUST
MAY CAUSE
SERIOUS BODILY HARM.

Order No. _____ F. O. _____

To _____

_____

_____

FROM

REDDAWAY MANUFACTURING CO., INC.

32 EUCLID AVENUE

NEWARK, NEW JERSEY 07105 U. S. A.