S.V. C.V. 901 903 D.V. 902,904

CG 32 CODE RT-761-D PKG 49

PROCESSES APPROVED BY
( ) RT-761-D ~~PHJ~~ ~~JJG 4-22-82~~
(I) ALTERNATE( )
( ) ~~XQB 2-1~~ ( )

1/5/82 (DATE) A2H61 (LOT NUMBER)

TYPED BY: JLC

EST. WT. ~~26400~~ 2737# LBS. STANDARD HRS. TIME 7A M

PREPARATION NOTES: _____

EQUIPMENT			USE LBS	N-CODE	ACCT LBS
		NAME: WATCHUNG RED B			
		NOTE: DO NOT START IF PRESS WILL NOT BE AVAILABLE WITHIN 3 HRS. AFTER MAKING MAKING SUPERVISOR TO REVIEW WITH P.R. SUPV. & RECORD:			
		PRESS WILL BE READY _____M____/_____PR SUP			
		START MAKING _____M_____/_____MAKG SUPV			
PREP 1	1	RECORD: _____BATCHES SINCE SPARKLER LAST CLEANED. AFTER 5 BATCHES, CLEAN, DRESS SPARKLER & PRECOAT WITH 15#	_____	777-A	_____
	2	OBTAIN FOR S 12		740-C	
	3	OBTAIN FOR S 27		82-C	
	4	INSTALL DV & CV RECORDER & CONTROLLER CHART			
921/931 2	5	RUN 16" (160G) WATER INTO V_____& ADJ TO 80-100 DEG F			
	6	ADD IN 2-3 MIN	110	99-A	110
	7	ADD IN 1-2 MIN	50	530-A	50
	8	STIR 5 MIN & RECORD: PH_____(9.5-10.5)			
	9	STIR 20 MIN OR LONGER TO DISSOLVE FOR S 29			
		NOTE: NOTIFY PRESS ROOM BEFORE ROPING OFF AREA UNDER V 922			
922 3	10	RUN 32" (680 G) WATER INTO V 922			
	11	WEIGH INTO V-926 & RUN IN M_____,_____%	_____	7-D	216
	12	TURN ON AGITATOR & STEAM & DUMP IN FROM S 21		740-C	1107
		LOT #100% %			
		_____ _____ _____	_____		
		_____ _____ _____	_____		
		_____ _____ _____	_____		
	13	DUMP IN	25	113-A	25
	14	DUMP IN	10	777-A	10
	15	HEAT TO 212-214 DEG F WATCH FOAM			

EQUIPMENT		PAGE 2 OF 4 CG 32 CODE RT-761-D (H)	USE LBS	N-CODE	ACCT LBS
922 3 CON'D	16	RECORD: BY_____MUST BE +, ADJ IF NEEDED ASSUME 50%	_____	7-D	_____
	17	STIR 30 MIN AT 212-214 DEG F, THEN SHUT OFF STEAM WATCH FOAM NOTE: RECORD: SPARKLER PRESSURE _____PSI IF NOT ZERO, NOTIFY SUPERVISOR			
	18	RECORD: HT_____F & REC_____F			
	19	CIRCULATE 15 MIN OR LONGER AT 190-195 DEG F THRU SPARKLER UNTIL SOL'N IS CLEAR. MAINTAIN AT 190-195 DEG F FOR S 24 RECORD: START_____, TOTAL MIN_____ CLARITY_____			
MISC 4	20	MEASURE_____UNITS IN V 928 FOR S 42 (MURIATIC ACID)M_____,_____%	_____	28-D	533
	21	WEIGH IN FT FOR S 45 M_____,_____%	_____	725-D	359
	22	WEIGH IN DRUM FOR S 53 (SODIUM NITRATE SOL)		725-D	42
904/CV 5	23	RUN 1" _____G WATER INTO V_____ NOTE: USE CV IF MTY. IF CV IS NOT MTY, USE V-904			
	24	WHEN S 19 COMPLETE, PUMP IN V 922 THRU SPARKLER. MAINTAIN V-922 AT 190-195 DEG F RECORD: START_____, TOTAL MIN_____			
902 6	25	RUN 56" (1566 G) WATER INTO V 902			
	26	WEIGH IN V 926 & RUN IN M_____,_____%	_____	7-D	682
	27	ADJ TO 70-90 DEG F & STIR 10 MIN TO DISSOLVE			
	28	SLURRY IN 30 GAL WATER & POUR INTO V 902 TRISULPHOIL SOAP D)	100	39-A	100
	29	STEAM EJECT IN V 921/931 FROM S 9			
922 & 904/CV 7	31	WHEN S 24 COMPLETE, SHUT OFF PUMP & INSERT FOOT PLUG IN V 922			
	32	RUN IN 10" (207 G) WATER & HEAT TO 190-195 DEG F.			
	33	CIRCULATE 15 MIN OR LONGER THRU SPARKLER UNTIL SOLUTION IS CLEAR			
	34	PUMP V 922 THRU SPARKLER INTO V 904/CV			
	35	RUN IN 5" (103 G) WATER INTO V 922 & HEAT TO 190-195 DEG F			
	36	CIRCULATE 15 MIN OR LONGER THRU SPARKLER UNTIL SOLUTION IS CLEAR.			
	37	PUMP V 922 THRU SPARKLER INTO V 904/CV			
	38	WHEN V 922 MT BLOW OUT SPARKLER INTO V904/CV			
	39	HEAT V 904 TO 165-170 DEG F FOR S 42 NOTE: IF N-740-C SOLUTION WAS PUMPED DIRECTLY FROM SPARKLER TO CV AT S'S 23 & 24 OMIT S'S 40-41			

C.V. 901,903 D.V. 902,904

CG 32 CODE RT-761-D PKG ___

PROCESSES
( ) RT-761-D (J)
( ) RT-838-D (I)
( ) ( )
TYPED BY: JLC

APPROVED BY
JJG 6/10/81

(DATE) (LOT NUMBER)

ESTIMATED WGT ~~2750~~ ~~2440~~ 2737# LBS. STANDARD HRS. TIME _____M

PREPARATION NOTES: _____

EQUIP MENT		NAME: WATCHUNG RED B	USE LBS	N-CODE	ACCT LBS
		NOTE: DO NOT START IF PRESS WILL NOT BE AVAILABLE WITHIN 3 HRS AFTER MAKING. MAKING SUPV TO REVIEW WITH P.R. SUPV. & RECORD: PRESS WILL BE READY _____M____/_____PR SUP START MAKING _____M_____/_____MAKG SUPV			
PREP 1	1	RECORD: _____BATCHES SINCE SPARKLER LAST CLEANED. AFTER 5 BATCHES, CLEAN, DRESS SPARKLER & PRECOAT WITH 15#	_____	777-A	_____
	2	OBTAIN FOR S 12		740-C	
	3	OBTAIN FOR S 27		82-C	
	4	INSTALL DV & CV RECORDER & CONTROLLER CHART			
	4A	CLOSE OVERFLOW OUTLET VALVE FOR DISTRIBUTOR LINE AT REAR OF VAT			
~~921~~	~~5~~	RUN 16" (160G) WATER INTO V 921 & ADJ TO ~~70~~ 20-100 DEG F			
2	~~6~~	~~ADD IN 2-3 MIN~~	115	99-A	115
	~~7~~	~~ADD IN 1-2 MIN~~	52	530-A	52
	~~8~~	~~STIR~~ STIR 5 MIN & RECORD: PH 10.2 (9.5-10.5)			
	9	STIR 20 MIN OR LONGER TO DISSOLVE FOR S 30			
		NOTE: NOTIFY PRESS ROOM BEFORE ROPING OFF AREA UNDER V 922			
922	10	RUN 35" (722 G) WATER INTO V 922			
~~3~~	11	WEIGH INTO V-926 & RUN IN M_____, 50.36%	449	7-D	226
	12	TURN ON AGITATOR & STEAM & DUMP IN FROM S 2		740-C	1157
		LOT #100% %			
		~~337~~ 339 ~~98.30~~	650	JAN 6, 1982	
		~~331~~ 321 ~~98.00~~	335		
		~~331~~ 197 ~~98.77~~	199		
	13	DUMP IN	25	113-A	25
	14	DUMP IN	10	777-A	10
	15	HEAT TO 212-214 DEG F WATCH FOAM			
	16	RECORD: BY ~~+~~ ____MUST BE +, ADJ IF NEEDED			
		ASSUME 50%	_____	7-D	_____

DUP050110439

922 3 CONT	14	STIR 30 MIN AT 212-214 DEG F, THEN SHUT OFF STEAM WATCH FOAM			
	15	NOTE: RECORD: SPARKLER PRESSURE 0 PSI IF NOT ZERO, NOTIFY SUPERVISOR			
	16	RECORD: HT 212 F & REC 112 F			
	17	CIRCULATE 15 MIN OR LONGER AT 190-195 DEG F THRU SPARKLER UNTIL SOL'N IS CLEAR.			
	18	MAINTAIN AT 190-195 DEG F FOR S 24 RECORD: START 2247, TOTAL MIN 15, CLARITY C			
MISC 4	20	MEASURE 20 UNITS IN V 928 FOR S 39 (MURIATIC ACID) M 28.8%	1928	28-D	557
	21	WEIGH IN PT FOR S 42 M 33.2%	1256	725-D	419
	22	WEIGH IN DRUM FOR S 48 (SODIUM NITRITE SOL)	126	725-D	42
~~904~~/CV 5	23	RUN 1* ____G WATER INTO V 701 NOTE: USE CV IF MTY. IF CV IS NOT MTY, USE V-904			
	24	WHEN S 19 COMPLETE, PUMP IN V 922 THRU SPARKLER. MAINTAIN V-922 AT 190-195 DEG F RECORD: START 2320, TOTAL MIN 35			
902 6	25	RUN 56* (1566 G) WATER INTO V 902			
	26	WEIGH IN V 926 & RUN IN M 50.3%	1459	7-D	735
	27	DUMP IN FROM S3 LOT 7301 6371	1000 56	82-C	1056
	27A	WEIGH ON POSTAL SCALE & ADD LOT 10331	18	180-C	18
	28	ADJ TO 70-90 DEG F & STIR 10 MIN TO DISSOLVE			
	29	SLURRY IN 30 GAL WATER & POUR INTO V 902 TRISULFHOIL SOAP D)	105	39-A	105
	30	STEAM EJECT IN V 921/[redacted] FROM S 9			
922 & ~~904~~/CV 7	31	WHEN S 24 COMPLETE, SHUT OFF PUMP & INSERT FOOT PLUG IN V 922			
	32	RUN IN 12" (247G) WATER & HEAT TO 180-190 F			
	33	PUMP V 922 THRU SPARKLER INTO V ~~904~~/CV			
	34	WHEN V 922 MTY BLOW OUT SPARKLER INTO V ~~904~~/CV [redacted]	[redacted]	[redacted]	[redacted]
	36	HEAT V [redacted]/CV TO 165-170 DEG F FOR S 39 NOTE IF N-740-C SOL'N WAS PUMPED DIRECT FRM SPARKLR TO CV AT S'S23 & 24 OMIT S'S37 & 38			
CV 8	37	~~RUN IN 1* (95 G) WATER INTO V____~~			
	38	~~IF V 904 IS USED, PUMP V904 AT 165-170 F THRU UNDERSURFACE DISTRIBUTOR INTO CV AFAP (12-15 MIN) MAINTAIN CV AT 165-170 DEG F~~			
	39	RUN IN N-28-D FROM S20 IN 12-15 MIN			
	40	STIR 5 MIN			
	42	ADD TO 43" (4080 G) AT 32-38 DEG F (ICE)	50 (330	57-A	16500
	43	RUN IN N-725-A FROM S 21 AFAP (5-10 MIN)			
	44	STIR 30 MIN AT 32-38 DEG F MAINTAINING +CR, +KI RECORD: TIME START 5:10 PM			
		CR +___(+) KI +___(+)			

DUP050110440

EQUIP MENT		PAGE 3 OF 3 CG 32 CODE RT-761-D (J)	USE LBS	N-CODE	ACCT LBS
CV 8 CONT		NOTE:			
		(1) IF CR-,KI-, ADD 20% "AS IS" INCREMENTS ASSUME 32% RECORD: CR_____(+), KI_____(+)		28-D	
		(2) IF CR+,KI-, ADD 20% "AS IS" INCREMENTS ASSUME 33% RECORD: CR_____(+), KI_____(+)		725-A	
	44	DUMP IN (CALCIUM CHLORIDE)	1166	20-A	1166
	46	DUMP IN (STRONTIUM NITRATE)	255	246-D	255
	48	DUMP IN (BLANC FIXE)	135	65-A	135
	47	ADD FOR MAINTAINING 32-38 DEG F DURING COUPLING	10 36 X330	57-A	3300
902 9	48	POUR N-725-D FROM S 22 INTO V 902			
	49	DUMP IN (AMMONIUM CHLORIDE)	189	165-A	189
CV 10	50	IMMEDIATELY COUPLE V 902 THRU UNDERSURFACE DISTRIBUTOR INTO CV IN 18-22 MIN. MAINTAIN DV AT 32-38 DEG F (OPEN VALVE 1-1/4 TURNS)			
		RECORD: START 556PM TOTAL MIN 24			
	51	STIR 30 MIN & RCRD: BASE +___(+), DIAZO ___(-), PH 10.2 (10.0-10.5)			
	52	IF NECESSARY, ADJ TO PH (10.0-10.5) & RECORD: PH_____ ASSUME 50%		7-D	
		ASSUME 32%		28-D	
	53	WEIGH IN DRUM & POUR IN (ISO OCTANOL)	45	500-D	45
	54	HEAT TO 174-176 DEG F IN 70-75 MIN			
	55	RECORD: HT_____F & REC 175 F (AT SOF, OPEN WATER SPRAYS 1 1/4 TURNS)			
	56	STIR 30 MIN AT 174-176 DEG F			
	57	AFTR 10 MIN S56 STIR RCRD: PH 9.5 (9.5-10.0)			
	58	IF NECESSARY, ADJ TO PH 9.5-10.0 ASSUME 50% RCRD PH_____ IF PH ABOVE 10.0 DO NOT ADJUST		7-D	
	59	WHEN S 56 COMPLETE, FLOOD TO 180-190° (+,- 18,000 G) & STOP AGITATOR & TURN OFF WATER SPRAYS			
	60	OPEN WATER VALVE AT OVERFLOW FOR DISTRBUTR AND BACK FLUSH THRU CHECK VALVE AND DISTRIBUTOR FOR 2 MINUTES. SHUT OFF WATER.			
	61	OPEN OVERFLOW OUTLET VALVE FOR DISTRIBUTOR REAR OF VAT.			
		WHEN INSTRUCTED BY PROCESSING AREA HALFWAY THRU PRESSING			
		(1) DUMP IN	10	500-A	10
		(2) STIR 5 MIN			
		(3) ADVISE PROCESSING TO RESUME PRESSING			

START	FIN	OPTR
2:00 P 3:00 P.M.	3:0 P 9:45 P.M.	391


DUP050110441

EQUIPMENT		PAGE 3 OF 4 CG 32 CODE RT-761-D (H)	USE LBS	N-CODE	ACCT LBS
CV 8	40	RUN 1* (95 G) WATER INTO V_____			
	41	IF V 904 IS USED, PUMP V 904 AT 165-170 DEG F THRU UNDERSURFACE DISTRIBUTOR INTO CV AFAP (12-15 MIN) MAINTAIN CV AT 165-170 DEG F			
	42	RUN IN N-28-D FROM S 20 IN 12-15 MIN			
	43	STIR 5 MIN			
	44	ADJ TO 43* (4080 G) AT 32-38 DEG F (ICE)	45X330	57-A	_____
	45	RUN IN N-725-A FROM S 21 AFAP (5-10 MIN)			
	46	STIR 30 MIN AT 32-38 DEG F MAINTAINING +CR, +KI RECORD: TIME START_____CR_____(+) KI_____(+)			
		NOTE: (1) IF CR-,KI-, ADD 20# *AS IS* INCREMENTS ASSUME 32% RECORD: CR_____(+), KI_____(+)	_____	28-D	_____
		(2) IF CR+,KI-, ADD 20# *AS IS* INCREMENTS ASSUME 33% RECORD: CR_____(+), KI_____(+)	_____	725-A	_____
	47	DUMP IN (CALCIUM CHLORIDE)	1116	20-A	1116
	48	DUMP IN (STRONTIUM NITRATE)	244	246-D	244
	49	DUMP IN (BLANC FIXE)	130	65-A	130
	50	ADD FOR MAINTAINING 32-38 DEG F DURING COUPLING	30X330	57-A	_____
	51	DUMP IN FROM S 3 LOT _____ _____ _____ _____	_____ _____ _____ _____	253-C	972
	52	WEIGH ON POSTAL BALANCE AND DUMP IN AND STIR 10 MIN (1-HYDROXY-2-NAPTHOIC ACID)	40	180-C	40
902 9	53	POUR N-725-D FROM S 22 INTO V 902			
	54	DUMP IN (AMMONIUM CHLORIDE)	189	165-A	189
CV 10	55	IMMEDIATELY COUPLE V 902 THRU UNDERSURFACE DISTRIBUTOR INTO CV IN 38-42 MIN. MAINTAIN DV AT 32-38 DEG F (OPEN VALVE 1-1/4 TURNS) RECORD: START_____,TOTAL MIN_____			
	56	STIR 30 MIN & RECORD: BASE_____(+), DIAZO_____(-) PH_____(9.5-10.0)			
	57	IF NECESSARY, ADJ TO PH 9.5-10.0 & RECORD: PH_____ ASSUME 50%	_____	7-D	_____
		ASSUME 32%	_____	28-D	_____
	58	WEIGH IN DRUM & POUR IN (ISO OCTANOL)	45	588-D	45
	59	HEAT TO 184-186 DEG F IN 70-75 MIN			
	60	RECORD: HT_____F & REC_____F			
	61	STIR 30 MIN AT 184-186 DEG F			
	62	AFTER 10 MIN S 61 STIR, RECORD: PH_____(9.5-10.0)			


EQUIPMENT			USE	N CODE	ASST LBS
CV 10 CONT'D		PAGE 4 OF 4 DEPT 052 CODE RT-781-B CH[redacted]			
		[redacted]			
		[redacted] 10.0 DO NOT			
		ADJUST			
	64	[redacted] COMPLETE FLOOR TO 190°			
		(+,- 18000 CT) & STOP AGITATOR			
	65	OPEN DISTRIBUTOR GAP			
		WHEN INSTRUCTED BY PROCESS AREA HALFWAY			
		THRU PRESSING			
		(1) DUMP IN [redacted]			
		[redacted] F MIN [redacted]			
		(3) [redacted] PRESSING			

	STAGE	FINISH	OPTR


DUP050110443



DUP050110444



DUP050110445



DUP050110446