July 24, 1975

Dr. Donald J. Schneider
Chief Technical Director
Fort Howard Paper Company
1919 South Broadway
P. O. Box 130
Green Bay, Wisconsin 54305

Dear Dr. Schneider:

In your recent letter to David Wood you requested information relating to procedures we follow in containing spills in our PCB manufacturing facilities.

We have no formal written procedure but rely on the proper design of our facilities and emphasize prompt maintenance and a high level of good housekeeping. At all times we insist that our employees follow the proper industrial hygiene practices of wearing protective clothing, removal of contaminated clothing and thorough personal cleanliness.

I have attached a copy of the American National Standard Institute's Guidelines for Polychlorinated Biphenyls, a copy of Monsanto's recent issuedof the "Transformer Askarel Inspection and Maintenance Guide" and a copy of a presentation we made to an advisory committee to the EPA. I believe you will find in these articles the basic principles which must be followed to insure proper containment.

If I can be of further service please let me know.

Sincerely,

W. B. Papageorge
Manager, Product Acceptability
Specialty & Process Chemicals

WBP:pd
cc: David Wood

BB LL
MM

DSW 020555

STLCOPCB4008482