

INTER-OFFICE CORRESPONDENCE

TO: J. M. Kapura
 FROM: Jim Kucera
 SUBJECT: WEST PLANT STATUS/PROGRESS REPORT

GAY
 OFFICERS Safety
 PERRYMAN
 DATE: 01/20/84
 LOVELESS

RETURN TO

The following safety related items are listed along with their status and progress:

Fire Hose Reels

During the recent freeze several hard rubber hoses on the fire hose reels suffered damage to the equipment either by split hoses or cracked elbow joints. All of this equipment has been repaired and is in operable condition. *Not drained properly &/or leaky valves*

Safety Showers

All safety showers in the plant experienced some form of freeze damage. The brand of showers that we use are not comparable to the ones in the east plant. Plus they were a combination of two different brands. We still will have different brand parts on the showers when they become operable. Most of the broken parts have been replaced by Encon shower parts. This is to try and standardize the showers to be the same as the ones in the east plant. At least one shower in each process unit has been repaired and is in use. We are now in an interim stage waiting for parts to be delivered from the vendor and parent company supplier. We expect to have all showers operable in three to four weeks.

CH/W-000508

Deluge Systems

Immediately following the freeze, the damage to the system was investigated. Sepecial parts had to be orderd from the company that sold and installed the system. The parts were found in San Antonio, Atlanta and California. They were expedited to us by the Automatic Sprinkler Corporation. We now have all of the deluge systems broken valves, strainers, and pipes replaced. Each individual system will be tested to examine for unobserved damage. They can now be activated and are operable for any emergency because any leak would be of minor stature.

RECEIVED

JAN 23 1984

SAFETY & LOSS
CONTROL DEPT

Tank Farm Walkways

A EWO has been initiated toward resolving this problem. As of this moment this is our most serious potential safety hazard. We are also in direct violation of OSHA's Part 1910 Sub Part D - Walking/Working Surfaces. *don't say this ever*

Sulfur Stack Extention

This project has been completed. Although we will not actually know if the problem has been solved until our perennial south east winds arrive and we emit SO₂ from the stack.

Lost Time Record

As of January 19, 1984 we have worked 380 days without a lost time accident.

Reportables for 1984

None

First Aid Cases for 1984

None

Jim Kucera

Jim Kucera
Safety Engineer
West Plant

ss

cc: J. W. Bryant
~~J. W. Bryant~~
T. J. Grgurich
R. A. Loveless
B. D. Routh
File

CH/W-000509