

+ 1. Emulsion

A. Potential problems

Military - Good (passable mtd) submitted to Navy as
Turbine/ 1223

Industrial Customers

- Central Foundry } 500,000 lbs/yr.
 - Johnson Motors } 1,000,000 lbs/yr
 - Chery - Bay City } 500,000 lbs/yr.
 - Chery - Messina } 750,000 lbs/year
- Some steel accounts

Reclaimers

Findlett
Redco

2. B. Solution - Alternatives

- Soft water - no silicic (all HSCP)
- Soft water - majority of production silicic when necessary
- Higher PCP assay

2. Lubrication - LFW test

Still unresolved on LFW OK on

Dig water into only if Texas Eastern does not test Turbulence

3. Hydrolytic Stability

No problem on SOE on Turbine 1223

+ 4. Plavolins

work to determine cause of higher ^{plavolins} values with ester

A. higher assay PCP from Kearing (98%)

B. Further work on ^{test} methods and analytical methods

0065728