

B

ASBESTOS - SAFETY AND REMOVAL

Primarily Products

000385 - 006007

000385	Bag Markings - Caution Notice 1/17/70
000600-000603	Asbestos Assemblies vs. Other Roofing Assemblies
000676	Notice for caution in handling Hydra Seal 1042 8/7/73
000849-000850	Letter regarding products to replace or extend asbestos 7/17/75
001052-001053	Letter & article regarding asbestos controversy to Plastics Design Forum; PVC Market Development 2/2/79
001171	Memo - Bird & Son using asbestos in roof coatings & cements 9/3/82
001172	Memo - Substitute for Asbestos Fiber in Bird Cements & Roof Coatings 9/2/82
001179-88	Memo - raw material cost of replacing asbestos with Hercules Pulpex 11/2/82
001189	Memo - substitute for asbestos in Bird cements & roofcoatings
001232	Memo - Cost of replacing asbestos with Hercules Pulpex 11/3/82
001233	Memo - Samples of FS cement production for asbestos replacement work 1/10/83
001234-001235	Memo - Updated cost of replacing asbestos with Hercules Pulpex
001304-5	Rules regarding caution labels 3/31/86
001426-48	Banning of Asbestos Products & Reporting Requirements 10/19/91
006005-07	Asbestos Containing Roofing Products 9/24/87