

Abex

Abex Industries Corporation

Abex Corporation
Friction Products Division
Suite 710
3001 West Hwy. Beaver Rd.
Troy, N.Y. 12180
(518) 643-4400

March 16, 1981

Mr. Paul L. LeCour
RAYLOC
P.O. Box 43146
Atlanta, Ga. 30336

Dear Paul:


This is to confirm our conversation regarding strip lining specifications which appear to be too thick to work on many import applications.

As you know, I asked Francis Hudson to assist in the endeavor to find a solution to the problem. It appears from my discussions with him that the course of action to determine how much can be ground off by American Brakeblok and Rayloc was acceptable.

If there is anything else that we can do to further assist in resolving this issue, you may contact Francis direct and copy me and if you are not completely satisfied, re-contact me directly by phone.

Looking forward to seeing you soon.

Best regards,


R. D. Ward,
Vice President -
Aftermarket Sales

/mc

cc: J. E. Aderhold
R. V. Bagley
D. Daniel
H. Dunn
P. H. Grim
F. Y. Hudson
J. W. McCool
L. W. Moore

NAPA 010

NOVO10733

SCF-NAPA-1640