G.M Yeen info

Will Give V.P.M @ 0900 [illegible]

7 Sep 71

Change out Therminol FR-2 to T-66 in the Aroclor Dept.

---

Provide vent & flame arrester for main (4000 gal) surge tank located in building beneath Solid Aroclor system; Tie in six satellite T-66 systems (used for cooling). Includes $N_2$ blanketting of main surge tank & diking of Therminol heater & remote switch for pumps NFC = $21800

Provide sprinkler system for main surge tank NFC = $3500

Provide flame arrester for Solid Aroclor Packaging area NFC = $1000

Misc items - operator training & change out labor, drums etc Expense $2000

Totals NFC $26300
Expense 2000

Cost of HB-40 ~7500 gals = (5000)

Sol Aroclor DT = Tiu in + Chg
J-5 Dean (?)

DSW 552062

STLCOPCB4090479