FILE NAME: Reynolds Metals (RM)

DATE: 1986 Jan 20

DOC#: RM026

DOCUMENT DESCRIPTION: Memo - Asbestos in the Plant that is Exposed

RAPID MEMO

FOR Handwritten MESSAGES (MAY ALSO BE TYPED)

REYNOLDS METALS COMPANY

2

FROM: S Hayes

TO: Tom King

INSTRUCTIONS — ADDRESSOR RETAIN THIS COPY FOR FOLLOW-UP

SUBJECT: Asbestos in the Plant that is Exposed

DATE: 1/20/82

MESSAGE

There several places in the plant that have exposed Asbestos insulation - i.e Pipes, Tanks, vessels that have lost the "Cover" over the insulation exposing the Asbestos

To List A Few -

AREA I - The S.O.P. TANK
Various STEAM Lines

AREA II - Flash TANKS
Oscilators
STEAM & Liq LINES
Digester Fd TANKS

AREA III - Filter Fd TANKS (1 thru 4)
washer & Settlers
Liq Lines (washer & Sett Feed & Fb Lines)
STEAM Lines & TANKS thru out AREA

FOLD HERE

☐ REPLY IMMEDIATELY ☑ NO REPLY NECESSARY SIGNATURE

REPLY

AREA IV - # 9 ESP - (with exception of E & W side
1 thru 7 Kiln STACK (Dust coll & ESP.)
(# 1/2 & 3/4 Are mineral wool)
STEAM & Liq Lines Thru out AREA

Power - STEAM Lines -
Boilers -

While we Repair these problems or Attrition, we have no Established Program TO correct the Problem.

FOLD HERE

DATE REPLY FROM (SIGNATURE)

B.001403

R-98-2 (REV. 6-67)

(19)