David Wood-St. Louis-B2SD

February 24, 1976

PCB INCINERATION

D. L. Sliney

FEB 25 1976

~~C. Paton~~
R. G. Potter
W. Easley-1940

1. I attach a copy of the letter we send to customers inquiring about incineration of PCB fluids.

2. Also, attached is a copy of the label for return product waste and an advise note that we request be given to the carrier.

3. Companies who regularly make returns receive a wall chart to place in their shipping area to focus attention on good handling practice. I attach a reduced copy of the wall chart and a copy of the text.

4. We do have problems with return in bad drums from time to time, and J. C. Weber is developing a procedure to handle these cases.

David Wood

/deb
Attachments

DSW 337326